

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN THIS  
(Other instruction  
verse side)copy TO 37  
Fossil, record,  
Budget Bureau No. 42-R1424

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> P & A	6. LEASE DESIGNATION AND SERIAL NO. NM 0219603
2. NAME OF OPERATOR Yates Petroleum Corporation	7. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR 207 South 4th Street - Artesia, NM 88210	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface	8. FARM OR LEASE NAME Federal "BZ" Com
	9. WELL NO. 16
	10. FIELD AND POOL, OR WILDCAT Und Morrow
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 28-17S-25E Unit H NMMP
14. PERMIT NO. MAR 28 1977	12. COUNTY OR PARISH Eddy
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3550' GR	13. STATE NM

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

O. G. C. NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>	WATER SHUT-OFF	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	FRACTURE TREATMENT	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	SHOOTING OR ACIDIZING	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	(Other)	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>	ABANDONMENT*	<input checked="" type="checkbox"/>
CHANGE PLANS	<input type="checkbox"/>		<input type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

## 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

TD 8302' - This well was plugged and abandoned as follows:

Spotted cement plug in heavy mud at:	
8175-8025'	50 sacks
7250-7100'	50 sacks
5350-5200'	50 sacks
4100-4000'	35 sacks
2500-2400'	35 sacks
1600-1500'	35 sacks

The location will be cleaned according to BLM surface restoration stipulations.

RECEIVED

JAN 17 1977

U.S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

## 18. I hereby certify that the foregoing is true and correct

SIGNED Christine Ambrose TITLE Geol. Secty DATE 11-16-77

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: