

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☒ gas well ☐ other ☐2. NAME OF OPERATOR
C.E. LaRue & Muncy, Inc.

3. ADDRESS OF OPERATOR

PO Box 470 Artesia, NM 88210

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: E₁-SE₄ 6-0-0/2

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) _____

SUBSEQUENT REPORT OF:

☐
☐
☐
☐
☐
☐
☐
☐

5. LEASE

LC064023

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Saunders lease

9. WELL NO.

9 & 10

10. FIELD OR WILDCAT NAME

Red Lake 9-5-0A

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

S-13, T-17S, R-27E

12. COUNTY OR PARISH

Eddy

13. STATE

NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

3548 GL

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Excess Junk, as cited by BLM in September of 1985, was removed by Operator to the extent Operator had legal ability to do so. LaRue & Muncy did not and do not own, nor were responsible for, material remaining on lease surface. Other individual(s) were and are in legal title to said material. It is unknown by this Operator who said individuals are.

A meeting between C.E. LaRue, of LaRue & Muncy, and Mr. Valdez of the BLM and BLM representatives from Santa Fe, NM was held in 1986 on lease site. At that time it was agreed that LaRue & Muncy had completed their portion of necessary clean up.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED C.E. LaRue TITLE Operator

ACCEPTED FOR RECORD

DATE 4-17-87

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE 65

CARLSBAD, NEW MEXICO