

NEW MEXICO OIL CONSERVATION COMMISSION RECEIVED

MAR 21 1977

O. C. C.

SUNDRY NOTICES AND REPORTS ON WELLS ARTESIA, OFFICE

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - M" (FORM C-101) FOR SUCH PROPOSALS.)

5a. Indicate Type of Lease

State ☐

Fee ☒

5. State Oil & Gas Lease No.

7. Unit Agreement Name

8. Farm or Lease Name

Friendly Frenchman Hill

9. Well No.

1 1

10. Field and Pool, or Wildcat

Und. Morrow

12. County

Eddy

15. Elevation (Show whether DF, RT, GR, etc.)

3374' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

TEMPORARILY ABANDON ☐

PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐

CHANGE PLANS ☐

OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

COMMENCE DRILLING OPNS. ☐

CASING TEST AND CEMENT JOB ☐

OTHER Set Production Casing ☒

ALTERING CASING ☐

PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 8050'; PTD 8008'; PETD 7928'. Ran 245 joints of 4½" 11.6# & 10.5# K-55 casing as follows: 30 joints of 11.6# (1172'), 213 joints 10.5# (6742') and 2 joints 11.6# (64') (Total 7978') set at 7960' KB, 1-Guide shoe at 7960 and float collar at 7928'. Cemented as follows: 500 gallons mud flush, 300 sacks of Halliburton Lite + .5% CFR-2 + 5#/sx KCL, 400 sacks of Class H + .5% CFR-2 + 5#/sx KCL displaced w/40 bbls KCL water and 87 bbls fresh water. PD 11:16 AM 2-15-77. Bumped plug w/1700# and set slips. WOC and ran Temperature Survey and found top of cement at 5200'. WLPBTD 7930'.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

*Christine Tomlinson*

TITLE

Geol. Secty

DATE

3-19-77

APPROVED BY

*W.A. Gressett*

TITLE

SUPERVISOR, DISTRICT II

DATE

MAR 22 1977

CONDITIONS OF APPROVAL, IF ANY: