

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPL
(Other instructions
reverse side)E*
re-Copy to SF
Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

0559535

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal "FR"

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Square Lake (GBC. S.A.)

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 28-16S-30E

Unit H NMPM

12. COUNTY OR PARISH 13. STATE

Eddy

NM

1. RECEIVED

OIL
WELL ☒ GAS
WELL ☐ OTHER

2. NAME OF OPERATOR

Yates Petroleum Corporation

MAR 24 1977

3. ADDRESS OF OPERATOR

207 South 4th Street - Artesia, NM 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1980' FNL & 660' FEL of Sec. 28-16S-30E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3772 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Spud

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Spudded a 12 $\frac{1}{4}$ " hole at 4:00 PM 3-9-77.

TD 315'' Ran 8 joints of 8-5/8" J-55 24# (315') of casing set at 315' KB.
1-centralizer at 250' and 1-basket at 175'. Cemented w/200 sacks of
Class C 4% CaCl. Cement circulated approx. 40 sacks to pit. PD 7:15
AM 3-11-77. WOC 18 hours, nipples up, tested BOP's to 1000#. OK. Reduced
hole to 7-7/8", drilled plug and tested to 600#. OK. Resumed drilling.

RECEIVED
MAR 21 1977
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Christine Tomlinson

TITLE Geol. Secty

DATE 3-19-77

(This space for Federal or State office use)

APPROVED BY

Lee S. Lam

TITLE ACTING DISTRICT ENGINEER

DATE MAR 23 1977

CONDITIONS OF APPROVAL, IF ANY: