

UNITED STATES DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

ARTESIA, NEW MEXICO
(Other Instructions on reverse side)

copy to SF
Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 0559535

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal "FR"

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

Square Lake (GBG.S.A.)

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Section -

28-16S-30E

Unit J NMPM

12. COUNTY OR PARISH 13. STATE

Eddy

NM

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Yates Petroleum Corporation

3. ADDRESS OF OPERATOR

207 South 4th Street - Artesia, NM 88202

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface

1980' FSL & 1980' FEL of Section 28-16S-30E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3763' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Spud

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded a 12 1/4" hole at 4:00 PM 3-29-77.

TD 476' - Ran 12 joints of 8-5/8" 24# J-55 (476') of casing set at 476'. 1-Texas Pattern shoe. Cemented w/300 sacks of 4% CaCl. Cement circulated 20 sx to surface. PD 3:30 PM 3-30-77. Cement fell and filled hole w/3 yards of Ready-mix. WOC 18 hours, nipples up. Tested BOP's to 1000# OK, reduced hole to 7-7/8", drilled plug and tested to 600# OK, resumed drilling,

RECEIVED
APR 08 1977
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Geol. Secty

TITLE

DATE

4-8-77

(This space for Federal or State office use)

APPROVED BY

TITLE

ACTING DISTRICT ENGINEER

DATE

APR 11 1977

CONDITIONS OF APPROVAL, IF ANY: