

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO.
30-015-22487

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
E-7842

7. Lease Name or Unit Agreement Name
Empire Abo Unit "E"

8. Well No.
361

9. Pool name or Wildcat
Empire Abo

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3671.6' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
ARCO Permian

3. Address of Operator
P.O. Box 1089 Eunice, NM 88231

4. Well Location
Unit Letter **A** : **620** Feet From The **N** Line and **1200** Feet From The **E** Line
Section **34** Township **17S** Range **28E** NMPM **Eddy** County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	


12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD: 6294' PBD: 6274' PERFS: 6020-6030'

09/18/98: Ran CBL. Indicated csg parted @ 3475'. Ran MSC log indicated parted csg @ 3475'.

09/21/98: RIH w/RBP Set @ 2861'. Load csg. Press up on plug held good. Dump 2 sxs sand on RBP. Awaiting Engineering Evaluation. Well Remains in TA status.

Well shut-in waiting on repair.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kellie D. Murrish TITLE Administrative Assistant DATE 06/28/99
TYPE OR PRINT NAME Kellie D. Murrish TELEPHONE NO. 505-394-1649

(This space for State Use)

APPROVED BY Mike Stuebel TITLE Field Rep II DATE 7/27/99
CONDITIONS OF APPROVAL, IF ANY: