REVISED 9-12-78		· REVISED 9-12-78
NO. OF COPIES AFCEIVED	NEW MEXICO OIL CONSERVATION	Form C-103 Superseders ()Id C-102 und C-103 Effective 1-1-65
FILE / U.S.G.S.		1 4 1978 Sa. Indicate Type of Lease State Fee X S. State Oil & Gas Lease No. Sa.
SUN (DO NOT USE THIS FORM FOR USE "APPLI		C. C. A, OFFICE T. Unit Agreement Name
OIL CAB WELL WELL X 2. Name of Operator BEARD OIL COMPANY // 3. Address of Operator	07HER-	8, Farm or Lease Name McCaw 9, Well No.
2000 Classen Center, 4. Location of Well	1980 North] 10. Field and Pool, or Wildcat
	15. Elevation (Show whether DF, RT, GR, etc.) 3857' RKB	12. County Eddy
	k Appropriate Box To Indicate Nature of Notice питептион то:	, Report or Other Data SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK		
12 Describe Described on Completed		at data including antimated data of starting one proposed

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1903.

Well was spudded at 9:00 A. M. on 6-13-78. A $17\frac{1}{4}$ " hole was drilled to 241'. 13-3/8", 54#, H-40 casing was set at 241' and cemented with 250 sacks Class "C" cement; cement circulated. WOC 12 hrs; bump plug at 1000# pressure; held o. k. An 11" hole was drilled to 1020' and 8-5/8", 24#, K-55 casing was set @ 1018' and cemented with 370 sacks LtWt plus 200 sacks of Class "C" cement; cement circulated. WOC 18 hrs; pressure tested casing and BOP stack to 1000 psi; held o. k. A 7-7/8" hole was drilled to 7140' total depth. Logs were run and $4\frac{1}{2}$ " casing was set at 7140' (6805.49' of 10.5#, K-55 and 334.51' of 11.6#, K-55, ST&C) and cemented with 210 sacks of Class "C" cement. Plug was down at 11:15 A. M. 7-7-78. Pressure tested casing to 2000 psi, held o. k. Waited on cement 48+ hours. Found top of cement at approximately 6170' on $4\frac{1}{2}$ " casing.

Perforated Atoka sand from 7032-36' and 7054-62' w/2 holes/ft. Treated perforations with 500 gals. 15% HCl. Gauged 600 MCFG after acid treatment. Fracture treated with 18,000 gals of 3% gelled acid water and 23,000# of 20/40 sand down tubing under a packer. After cleaning well up ran 4-point open flow test. Open flow potential = 3,733 MCFGPD.

18. I hereby certify that the information above is true and com	Vice President	DATE	8-30-78
PROVED BY W. G. Gresset	THE SUPERVISOR DISTRICT II	DATE	SEP 1 4 1978