

Copy to 87

Form 9-331
(May 1963)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 7050

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT..." for such proposals.)

RECEIVED

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Yates Petroleum Corporation ✓

3. ADDRESS OF OPERATOR

207 South 4th Street - Artesia, NM 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)

At surface

1980' FSL & 1980' FWL of Section 4-17S-24E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3755' GR

8. FARM OR LEASE NAME

Divide Fed JW Com

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Und. Atoka

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 4-17S-24E

Unit K NMPM

12. COUNTY OR PARISH 13. STATE

Eddy

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TD 1050' - Ran 26 joints of 8-5/8" 24# K-55 (1068') of casing set at 1050'.
1-Float Shoe at 1050'. 1-centralizer at 1050'. 2-Baskets at 822 and 340'.
Cemented w/350 sacks of Denton-Lite cement followed w/165 sacks of Ches
C 2% CaCl. Cement circulated 15 sacks to surface. PD 12:45 PM 8-5-78.
WOC 42 hours, nipples up and tested BOP's to 1000#. OK. Reduced hole to
7-7/8", drilled plug and tested to 600#. OK. Resumed drilling.

RECEIVED
AUG 8 1978
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Christie Johnson

TITLE

Geol. Secty

DATE 8-8-78

(This space for Federal or State office use)

(Orig. Sgd.) ALBERT R. STALL

TITLE

ACTING DISTRICT ENGINEER

DATE AUG 11 1978

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side