

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE\*  
(Other instruction on reverse side)Copy to SF  
Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 7050

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Yates Petroleum Corporation ✓

DEC - 8 1978

3. ADDRESS OF OPERATOR

207 South 4th Street - Artesia, NM 88210 D.C.C. OFFICE

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface

1980' FSL &amp; 1980' FWL of Section 4-17S-24E

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Divide Fed. JW Com

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Unit Wolfcamp

11. SEC., T., R., M., OR BLK. AND

SURVEY OR AREA  
Sec. 4-17S-24E

Unit K NMMP

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3755' GR

12. COUNTY OR PARISH

Eddy

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐  
☐  
☐  
☐

PULL OR ALTER CASING

☐  
☐  
☐  
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐  
☐  
☐  
☐

REPAIRING WELL

☐  
☐  
☐  
☐

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT\*

(Other)

Set 4½" Prod. Csg. X

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

9-18-78 - TD 7141' - Ran 160 joints of 4½" K-55 10.5# (6908') of casing set at 6906', diff-fill collar at 6865'. Guide shoe at 6906'. 8-centralizers. Cemented as follows w/175 sacks of Class C 3#/sack KCL, 5/10% CFR-2, 2/10% Halad-22, 300 sacks of Howco-Lite, 3#/sack KCL, 5/10% CFR-2, 2/10% Halad-22, 150 sacks Class C 3#/sack KCL, 5/10% CFR-2, 2/10% Halad-22. PD 10:30 AM 9-18-78. Ran Temperature Survey and found top of cement at 3700'. Tested to 1500#. OK

RECEIVED  
DEC 5 1978  
U.S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Christine Johnson

TITLE

Geol. Secty

DATE

12-4-78

(This space for Federal or State office use)

APPROVED BY

Lee J. Lara

TITLE

ACTING DISTRICT ENGINEER

DATE

DEC - 6 1978

CONDITIONS OF APPROVAL, IF ANY: