

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Drawer DD  
Artesia, NM

**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other

2. NAME OF OPERATOR

Mesa Petroleum Co. ✓

3. ADDRESS OF OPERATOR

1000 Vaughn Bldg. / Midland, TX 79701-4493

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 2080' FNL & 1650' FEL

AT TOP PROD. INTERVAL: Same

AT TOTAL DEPTH: Same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON\* ☐

(other) /X/ Bring risers up on 13-3/8" & 8-5/8" csg.

SUBSEQUENT REPORT OF:

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

|                                                                            |
|----------------------------------------------------------------------------|
| 5. LEASE<br>888107066                                                      |
| 6. IF INDIAN, ALLOTTEE OR TRIBE NAME                                       |
| 7. UNIT AGREEMENT NAME                                                     |
| 8. FARM OR LEASE NAME<br>Wells Federal                                     |
| 9. WELL NO.<br>2                                                           |
| 10. FIELD OR WILDCAT NAME<br>Diamond Mound Atoka                           |
| 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA<br>Sec. 11, T. 6S, R. 27E |
| 12. COUNTY OR PARISH<br>Eddy                                               |
| 13. STATE<br>New Mexico                                                    |
| 14. API NO.                                                                |
| 15. ELEVATIONS (SHOW DF, KDB, AND WD)<br>3642' GR                          |

RECEIVED  
OCT 16 1981

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

On 8/20/81, risers were brought up on the 13-3/8" and the 8-5/8" casing, and the cellars were filled with cement. The well was inspected by Michael Williams of the Artesia NMOC.

RECEIVED  
OCT 9 1981

OIL & GAS  
U.S. GEOLOGICAL SURVEY  
ROSWELL, NEW MEXICO

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_

18. I hereby certify that the foregoing is true and correct

SIGNED Cathy Wilkerson TITLE Prod. Recds. Analyst DATE 10/7/81

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

XC: USGS, TLS, MEC, LAND, CNT RCDS, ACCTG, D&M, PARTNERS, FILE

ACCEPTED FOR RECORD

OCT 15 1981

U.S. GEOLOGICAL SURVEY  
ROSWELL, NEW MEXICO