

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

RECEIVED
 NEW MEXICO OIL CONSERVATION COMMISSION
JAN 17 1979

Form C-103
 Supersedes Old
 C-102 and C-103
 Effective 1-1-65

O. C. C.
 ARTESIA, OFFICE

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. OG 181	
7. Unit Agreement Name	
8. Farm or Lease Name Lucas Store "JZ" St.	
9. Well No.	Com
1	1
10. Field and Pool, or Wildcat Und. Empire Penn	
12. County Eddy	

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
 USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- 2. Name of Operator Yates Petroleum Corporation 3. Address of Operator 207 South Fourth Street - Artesia, NM 88210 4. Location of Well UNIT LETTER <u>E</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>860</u> FEET FROM THE <u>West</u> LINE, SECTION <u>23</u> TOWNSHIP <u>17S</u> RANGE <u>28E</u> NMPM.	15. Elevation (Show whether DF, RT, GR, etc.) 3693' GR
---	---

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
 NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 10690'. This well was plugged and abandoned as follows:

1. 10350-10250' 35 sacks
2. 9200-9050' 50 sacks
3. 7950-7850' 35 sacks
4. 6970-6820' 50 sacks
5. 5930-5830' 35 sacks
6. 3920-3720' 70 sacks
7. 2650-2500' 50 sacks
8. 2300-2200' 35 sacks

10' surface plug w/5 sacks. Heavy mud was placed between each plug.
 Dry hole marker has been installed. The location will be cleaned, pits
 filled and levelled and ready for inspection. PLUGGED AND ABANDONED
1-12-79.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Christine Tomlinson TITLE Geological Secretary DATE 1-16-79

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: