

Form 9-331
Dec. 1973Form Approved.
Budget Bureau No. 42-R1424UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well gas ☒ well other ☐

2. NAME OF OPERATOR
Amoco Production Company ✓

3. ADDRESS OF OPERATOR
P. O. Box 68 - Hobbs, NM 88240

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
2080' FNL X 760' FEL, Sec. 33
AT SURFACE: (Unit H, SE/4 NE/4)
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:	SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF <input type="checkbox"/>	<input checked="" type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE <input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES <input type="checkbox"/>	<input type="checkbox"/>
ABANDON* <input type="checkbox"/>	<input type="checkbox"/>
(other) <input type="checkbox"/>	<input type="checkbox"/>

5. LEASE
NM-056122 **RECEIVED**

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
DEC 17 1979

7. UNIT AGREEMENT NAME
O.C.C.

8. FARM OR LEASE NAME
Federal "Z" Com **ARTESIA, OFFICE**

9. WELL NO.
1

10. FIELD OR WILDCAT NAME
Und. Logan Draw Morrow

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
33-17-27

12. COUNTY OR PARISH
Eddy

13. STATE
NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
3482.48 GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Moved in service unit 12-5-79. Spot 150 gal 10% acetic acid. Ran correlation log. Perforated 9456' - 9468', 9420' - 9450' with 4 JSPF. Currently flow testing.

RECEIVED**DEC 14 1979**U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Bob Davis TITLE Asst. Admin. Analyst DATE 12-12-79

(This space for Federal or State office use)

APPROVED BY GEORGE H. STEWART TITLE Assistant District Engineer DATE DEC 14 1979

CONDITIONS OF APPROVAL, IF ANY:

0+4 - USGS-A 1 - Hou 1 - Susp 1 - BD 1 - Hondo