

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.O.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

RECEIVED
APR 22 1980
O. C. D.
ARTESIA, OFFICE

Form C-103
Revised 10-1-78

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Collier Energy, Inc. ✓	8. Farm or Lease Name St. B-1111, Tr. 1
3. Address of Operator P. O. Box 798, Artesia, NM 88210	9. Well No. #8
4. Location of Well UNIT LETTER <u>H</u> , <u>2310</u> FEET FROM THE <u>North</u> LINE AND <u>330</u> FEET FROM THE <u>East</u> LINE, SECTION <u>22</u> TOWNSHIP <u>17S</u> RANGE <u>28E</u> NMPM.	10. Field and Pool, or Wildcat East Empire Yates 7-R
15. Elevation (Show whether DF, RT, GR, etc.) 3584.2	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

March 28, 1980: Ran 846' of 4 1/2" 9.5 casing. Cemented with 150 sacks Halliburton Light 6#salt, 6# gilsonite, 1/4# flocele. Follow with 100 sacks 50/50 pos 2% gel, 6# salt 3/10% CFR-2. Well did not circulate.

March 29, 1980: Ran temperature survey. Cement to top at 35'.

March 31, 1980: Ready mix with 4 yards surface.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Rhonda Parrish TITLE Secretary DATE April 21, 1980
APPROVED BY W.A. Gussitt TITLE SUPERVISOR, DISTRICT II DATE APR 23 1980
CONDITIONS OF APPROVAL, IF ANY: