UNITED STATES

NM OIL CONS.

CONNE	SSTOR
MIM	22277

NM-33277	, 0	W 1		~	·	44,	
		NM	- 1	33	2	7	7
		<u> </u>	_	<u> </u>	=	<u>-</u>	<u>-</u>

DEPARTMENT OF THE INTERIOR Drawer DD	NM-33277
GEOLOGICAL SURVEY	862 TOINDIAN, ALLOTTEE OR TRIBE NAME
C/5" GEOLOGICAL SORVE! AFTESIA, NA	RECEIVED
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different	- 001 1 6 1091
reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas X other	Derrick Federal
well 니 well ഥ other	9. WELL NO.
2. NAME OF OPERATOR	2
Mesa Petroleum Co. ✓	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Diamond Mound Morrow
1000 Vaughn Bldg. / Midland, TX 79701-4493	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA
below.) AT SURFACE: 2160' FNL & 660' FEL	Sec. 5, T16S; R28E
AT TOP PROD. INTERVAL: Same	12. COUNTY OR PARISH 13. STATE
AT TOTAL DEPTH: Same	Eddy New Mexico
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE.	14. API NO. 5 5 6 5 6 5 6 5 6 6 6 6 6 6 6 6 6 6 6
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	3652' GR 3669' RKB
TEST WATER SHUT-OFF	
FRACTURE TREAT	
SHOOT OR ACIDIZE	
PULL OR ALTER CASING	(NOTE: Report results of multiple completion or zone change on Form 9-330.)
MULTIPLE COMPLETE	
CHANGE ZONES	ကြောင်းသည်။ မြောင်းသည်။ မြောင်းမြောင်းသည်။ မြောင်းသည်။ မြောင်းမြောင်းသည်။ မြောင်းမြောင်းသည်။ မြောင်းမြောင်းသည်။
ABANDON*	
(other) /X/ Bring risers up on 13-3/8" & 8-5/8" csg	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state	all pertinent details, and give pertinent dates,
including estimated date of starting any proposed work. If well is di measured and true vertical depths for all markers and zones pertinent	rectionally drilled, give subsurface locations and
measured and true vertical depths for all markers and zones pertinent	t to this work.)
	그 그 그 그는 사용하는 그를 갖춘요한
On 8/21/81, risers were brought up on t	the 13-3/8" casing and the
8-5/8" casing, and the cellars were fil	
was inspected by Michael Williams of th	ne Artesia NMOCD:
المستحل المستحل المستحولا	
ולצלה לולילצלין	
007	1001
,}{} UCT 9	1981 利用 [1] [1] [4] [4] [4] [4] [4]
Cail.	
0.8.40 	
U.S. GEOLOGI. ROSMÆLL MEN	
Subsurface Safety Valve: Manu. and Type	
Subsurface Safety valve, Mariu, and Type	Set @ Ft.
18. I hereby certify that the foregoing is true and correct	그 그 그 그 그 그 생각 그 생각 그 그 그 그 그 그 그 그 그 그
SIGNED Athy Wilkerson TITLE Prod. Recds. And	31VStpare 10/6/81
SIGNED THE TIME AND AND	TIYOUNIEII/U/UI

(This space for Federal or State office use)

XC: USGS,TLS,MEC,LAND,CNT RCDS,ACCTG,D&M,PARTNERS,FILE

ACCEPTED FOR RECORD