€0/m 9–331 Dec. 1973			MN OIL CONS	. COMISSION	Form Approved.			
DCG. 1570	UNITED	Sres	Segmen DD [	- 0.03.0		Č.	318	
	DEPARTMENT O	F THE INTERIO	R Artesia. "]	NM-18831		<u>.</u>	<u> </u>	
العرب المن المن المن المن المن المن المن المن	GEOLOGICA	L SURVEY		6. IF INDIAN,	ALLOTTEE (	OR TRIE	BE NAME	 
C/ 51				C RECEIVE				
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)				7. UNIT AGRE	EMENT NA	ME 📜		
						<u> </u>	OCT	-1 6 198
reservoir. Use Fo	8. FARM OR L		E Site	유설됨				
1. oil	gas othe	_		Depco_Fe	deral	<u>====</u>	<u>_</u>	<b>C</b> . D.
well '	Wen other	<u> </u>		9. WELL NO.	6 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	5	ARTE	SIA, OFFICI
2. NAME OF				10. FIELD OR V	VII DOAT ÑA		2 2 2 <u>2</u> 2	<del></del>
Mesa Petroleum Co. V				1		1 * me!	<b>- 55</b> 8	
3. ADDRESS OF OPERATOR 1000 Vaughn Bldg. / Midland, TX 79701-4493				Diamond 11. SEC., T., R		-	SLIBVEA	OR
1000 V	aughn Bldg. / M	lidland, IX	/9/01-4493	AREA	., IV., OK EI	-N. AIVL	2 30KVL1	OR
4. LOCATION below.)	OF WELL (REPORT	LUCATION CLEAR	LY. See Space 17		I165 - R	28F5		
AT SURF	ACE: 2160'	FNL & 1980'	FWL, Lot 11	12. COUNTY O			ATE	<del></del>
	PROD. INTERVAL:	Same		Fddv	25 h#	- 7	Mexico	
AT TOTAL	DEPTH:	Same		14. API NO.	<u> </u>	⊋	경우학상	
16. CHECK A	PPROPRIATE BOX TO	INDICATE NATU	JRE OF NOTICE,		甲型过渡	~	<u> </u>	
REPORT,	OR OTHER DATA			15. ELEVATION	NS (SHOW	DF, K	B, AND	WD)
		OURGEOUENT	DEDODE OF	3622' GR		.,	1, 1, 1, 1	
-	R APPROVAL TO:	SUBSEQUENT	REPORT OF:			ų.		
TEST WATER FRACTURE TE		H				<u>د</u> ح		
SHOOT OR A	_					<u> </u>		
REPAIR WELL				(NOTE: Report	results of mu	ltiple cor	npletion or	zone
PULL OR ALT		Д,		change	on Form 9–3	30.) =		<u>r</u> .
MULTIPLE CO	_					÷		<u>}_</u>
ARANDON*	一	H		**		2		Ę.
(other) /X/	Bring risers (	<u>up on 13-37</u> 8"	% 8-5/8" cs	g. "			- F	erá No.
including	E PROPOSED OR CO estimated date of sta d and true vertical dep	arting any proposed ths for all markers	d work. If well is d and zones pertiner	lirectionally drilled to this work.)*	d, give substitution and the s	surface	locations	ates, and
	On 8/24/81, r	isers were br	rought up on	the 13-3/8"	casing	and t	he-	
	8-5/8" casing	. and the cell	llars were fi	lled with pe	ea grave	1. WC	)rk i	
	was inspected	by Michael V	Villiams of t	he Artesia 1	MMOCD.	 	1.12	
		57	नहालकार	<i>एक</i> जि		17		
			المام متام رسال متام الرا		379			
			$\mathbb{W}$	7		3		
			Ŋ OCT 91	981 ///		·	-	
		£_		أمسست		÷,		
			OIL & GA U.S. GEOLOGICA ROSWELL, NEW	AL SURVEY				Ft.
Subsurface S	afety Valve: Manu. and	1 type			Set	<u>w</u>	1. C . F	( b.
18. I hereby	certify that the foregoi	ng is true and corre	ect				. <u> </u>	
(1)			Prod.Recds.An	nalvst	10/6/8	31	ç, X	

(This space for Federal or State office use)

XC: USGS,TLS,MEC,LAND,CNT RCDS,ACCTG,D&M,PARTNERS,FILE

\_ TITLE

ACCEPTED FOR RECORD

U.S. GEOLOGICAL SURVEY ROSWELL, NEW MEXICO

\*See Instructions on Reverse Side