

HOLE DIFFICULTIES:

None

CONTRACTOR:

Warton Rig #2, Odessa, Texas
Tool Pusher: Don Tidwell

DRILLING SUPERVISOR FOR HUSKY:

R. V. Plato, Hobbs, New Mexico

CONSULTING GEOLOGIST FOR HUSKY:

W. J. Henry, Midland, Texas

<u>FORMATION TOPS:</u>	<u>DEPTH</u>	<u>DATUM</u>
Queen	628	+2896
Grayburg	984	+2540
San Andres	1405	+2119
Glorieta	2700	++824
Tubbs	4060	- 536
Abo	4803	-1279
Waltrop	6006	-2482
Bursaw	6792	-3268
Strawn	7858	-4334
Atoka	8244	-4720
(Morrow)	8318	-4794
Miss. Shale	8498	-4974
Miss. Chester Lime	8568	-5044
Miss. Lime (Osage-Mermac)	8686	-5162
Total Depth	8765	-5241

DRILLING BREAKS:

Grayburg @ 1275-80 broke from 2" to 1 1/2"/ft
Lost circ - possible frac - equivalent to
zone in Mesa #1 Sink which was potentialled
for 1,400 MCFCPD. Mesa gas analysis: Nitrogen - 54.297%
Methane - 39.36%
BTU - 530

Unable to buck line pressure - will have to be compressed - not producing this date.

MORROW: 8349 - 8367 4" to 2"/Ft. poor spls.
8445 - 8455 4" to 2"/Ft. poor spls.
8489 - 8499 5" to 2" - 3"/Ft. poor spls.

*Note drilling breaks are approximately 10' low to log depths in the Morrow.