

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S	<input checked="" type="checkbox"/>
LAND OFFICE	<input checked="" type="checkbox"/>
OPERATOR	<input checked="" type="checkbox"/>

RECEIVED BY
OIL CONSERVATION DIVISION
P.O. Box 1088
SANTA FE, NEW MEXICO 87501
O. C. D.
ARTESIA, OFFICE

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.

L-4199

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT-" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
Read & Stevens, Inc.

3. Address of Operator
P.O. Box 1518, Roswell, NM 88201

4. Location of Well

UNIT LETTER M . 660 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE. SECTION 13 TOWNSHIP 16S RANGE 31E NMPM

5. Elevation (Show whether DF, RT, GR, etc.)
4393.8' GL

7. Unit Agreement Name

8. Farm or Lease Name
Gulf West Mesa

9. Well No.
1

10. Field and Pool, or Wildcat

~~Unit~~ Bunker Hill Penrose Assoc

12. County
Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-7-84 Frac Penrose w/652,500 SCFN₂, perfs 3612'-3632', total load 262 BBLs, avg rate 6 BBLs fluid, total w/N₂ 20 BPM, avg press 2430psi, max 3000psi, total sand: 10-20 25,000#, 8-16 30,000#, ISIP 2640psi, 5min-2450psi, 10min-2400psi, 15min-2360psi, flowed back, recd approx 25 BBLs, died @ 9:30pm.

8-8-84 Wshd out 61' sand from 3591'-3652', 20' below perfs, cleaned up and hang on, trouble w/pump, took PU apart, swbd out w/#2, circ 175 BBLs.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED B. Stubbs TITLE Drilling & Production Manager DATE 8-14-84

APPROVED BY Original Signed By TITLE Leslie A. Clements

DATE AUG 17 1984

CONDITIONS OF APPROVAL, IF ANY: Supervisor District II