

| | |
|------------------------|--|
| NO. OF COPIES RECEIVED | |
| DISTRIBUTION | |
| SANTA FE | |
| FILE | |
| U.S.G.S. | |
| LAND OFFICE | |
| OPERATOR | |

RECEIVED

DEC 22 1980

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐ CAR WELL ☒ OTHER ☐

ARTESIA, OFFICE

Name of Operator

Yates Petroleum Corporation

Address of Operator

207 South 4th St., Artesia, NM 88210

Location of Well

 UNIT LETTER K 1980 FEET FROM THE South LINE AND 1980 FEET FROM
 THE West LINE, SECTION 14 TOWNSHIP 17S RANGE 26E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)

3312.5' GR

5a. Indicate Type of Lease

State ☐Fee ☒

5. State Oil & Gas Lease No.

7. Unit Agreement Name

8. Farm or Lease Name

Haldeman OU Com

9. Well No.

1

10. Field and Pool, or Wildcat Und

Kennedy Farms-Morrow

12. County

Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐PLUG AND ABANDON ☐REMEDIAL WORK ☐ALTERING CASING ☐TEMPORARILY ABANDON ☐COMMENCE DRILLING OPS. ☐PLUG AND ABANDONMENT ☐REPAIR OR ALTER CASING ☐CHANGE PLANS ☐CASING TEST AND CEMENT J-B ☒OTHER ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spudded a 17-1/2" hole at 12:45 PM 12-13-80.

TD 400' Ran 15 joints of 13-3/8" 48# K-55 ST&C casing set at 400'. 1-regular pattern guide shoe at 400'. Flapper insert float at 370'. Cemented w/400 sacks Class C 4% CaCl. Slurry weight 14.8, 1.32 cu ft/sack. Compressive strength at 70 degrees 1023 psi in 12 hours. PD 9:25 AM 12-14-80. Cement circulated 35 sacks to pit. WOC 12 hours. Backed off and reduced hole to 12-1/4". Drilled plug and tested to 600 psi, OK. Resumed drilling.

TD 1387' Ran 35 joints of 8-5/8" 24# K-55 ST&C casing set at 1337'. 1-regular pattern guide shoe at 1387'. Auto-insert float at 1347'. Cemented w/700 sacks 65-35 Poz, 8# Kolite, 1/4# celloflakes and 3% Cacl. Tailed in w/150 sacks Class C 2% CaCl. PD 11:45 PM 12-16-80. Cement did not circulate. WOC 6 hours. Ran Temperature Survey and found top of cement at 500'. Ran 1". Tagged cement at 403'. Spotted 75 sacks Class C 4% CaCl. PD 11:45 AM 12-17-80. Pulled 180' of 1". Spotted 105 sacks Class C 4% CaCl. PD 12:00 noon 12-17-80. Circulated 10 sacks to pit. Cement fell back. Filled hole w/4 yards of Ready Mix. WOC 18 hours. Nippled up and tested to 1500 psi, OK. Reduced hole to 7-7/8". Drilled plug and tested to 600 psi, OK. Resumed drilling.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

*Albert R.etal*TITLE EngineerDATE 12-22-80

For Record Only

APPROVED BY

W. A. Smith

TITLE

SUPERVISOR, ARTESIA

DATE

DEC 30 1980

CONDITIONS OF APPROVAL, IF ANY: