## N.M.O.C.D. COPY

Form 9–331 Dec. 1973	Form Approved. Budget Bureau No. 42–R1424 5. LEASE NM–0219603–A 6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
UNITED STATES DEPARTMENT OF THE INTERIOR		
GEOLOGICAL SURVEY		
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME	
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NAME	
1. oil well as under JAN 2 ≤ 1931	Federal BW 9. WELL NO.	
2. NAME OF OPERATOR	9	
Yates Petroleum Corporation $\sqrt{2}$	10. FIELD OR WILDCAT NAME	
3. ADDRESS OF OPERATOR	Eagle Creek SA	
207 South 4th St., Artesia, NM 88210	11. SEC., T., R., M., OR BLK. AND SURVEY OR	
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	AREA Unit O, Sec. 22-T17S-R25E	
AT SURFACE: 990' FSL & 1650' FEL	12. COUNTY OR PARISH 13. STATE	
AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	Eddy NM	
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO.	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)	
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	3523' GR	
TEST WATER SHUT-OFF		
FRACTURE TREAT	$\sum_{i=1}^{n} \sum_{j=1}^{n} \sum_{i=1}^{n} \sum_{i$	
SHOOT OR ACIDIZE	$\mathcal{Y}_{\mathcal{M}}$ .	
REPAIR WELL	(NOTE: Report results of multiple completion or zone change on Form 9–330.)	
	OC ALCO	
ABANDON*		
(other)	Na <sup>1</sup>	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Spudded a 15" hole at 4:30 PM 1-16-81.

TD 350' Ran 9 joints of 10-3/4" 40.50# K-55 ST&C casing set at 350'. 1-Notched guide shoe at 350'. Flapper insert float at 311'. Cemented w/250 sacks Class "C" 4% CaCl. PD 4:45 PM 1-16-81. Bumped plug to 500 psi, released pressure and float held okay. Cement circulated 35 sacks to pit. Compressive strength of cement = 1850 psi in 12 hours. WOC 12 hours. Reduced hole to 9-1/2". Drilled plug and resumed drilling.

1168' Ran 27 joints of 7" 20# K-55 ST&C casing set at 1168'. 1-notched guide shoe at 1168'. Flapper insert float at 1128'. Cemented w/400 sacks 65-35 Poz, % Bentonite, 8# Kolite, 1/4# celloflakes and 3% CaCl. Tailed in w/150 sacks Class "C" 2% CaCl. PD 1:30 AM 1-19-81. Bumped plug to 900 psi, released pressure and float held okay. Cement circulated 30 sacks to pit. WOC 18 hours. Nippled up & tested to 1500 psi, OK. Reduced hole to 6-1/4". Drilled plug & resumed drilling.

Subsurface Safety Valve: Manu. and	Туре	Set	@ Ff
N			

18. I hereby certify that the foregoing is true and correct

SIGNER Gam	ta Doo klill TITLE	Engineering <u>Secretary</u> DATE	Jan. 20, 1981
	ACCEPTED FOR REGORDACE PETER W. CHESTER	for Federal or State office use)	
CONDITIONS OF AF	JAN 2 3 1981		
	U.S. GEOLOGICAL SUR <b>VEY</b> Roswell, New Mexi <b>cq.</b> ,	structions on Reverse Side	