

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ gas ☐ other ☐
well well

2. NAME OF OPERATOR

Yates Petroleum Corporation ✓

3. ADDRESS OF OPERATOR

207 South 4th St., Artesia, NM 88210

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 330' FSL & 1650' FWL

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☐

(other) ☐

5. LEASE

NM 0219603-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal BW

9. WELL NO.

11

10. FIELD OR WILDCAT NAME

Eagle Creek SA

11. SEC., T., R., M., OR BLK. AND SURVEY OR

AREA
Unit N, Sec. 22-T17S-R25E

12. COUNTY OR PARISH

Eddy

13. STATE

NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

3536' GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded a 15" hole at 3:30 PM 1-25-81.

PD 348' Ran 9 joints of 10-3/4" 40.50# K-55 ST&C casing set at 348'. 1-notched guide shoe at 348'. Flapper insert float at 307'. Cemented w/250 sacks Class 40" 4% CaCl. PD 10:00 PM 1-25-81. Bumped plug to 500 psi, released pressure & float held okay. Cement circulated 45 sacks to pit. Compressive strength of cement 1850 psi in 12 hours. WOC 12 hours. Reduced hole to 9-1/2". Drilled plug & resumed drilling.

PD 1180' Ran 27 joints of 7" 20# K-55 ST&C casing set at 1180'. 1-Regular pattern guide shoe at 1180'. Flapper float at 1137'. Cemented w/600 sacks 65-35 Lite Poz III "C", 4% Bentonite, 8# Kolite, 1/4# celloflakes & 3% CaCl. Tailed in w/150 sacks Class 40" 2% CaCl. PD 4:00 PM 1-27-81. Bumped plug to 900 psi, released pressure & float held okay. Cement circulated 35 sacks to pit. WOC 19 hours. NU & tested to 1500 psi, okay. Reduced hole to 6-1/4". Drilled plug & resumed drilling.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Peter W. Chester TITLE Engineering Secretary DATE February 2, 1981

APPROVED BY _____

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

PETER W. CHESTER

FEB 3 1981

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

See Instructions on Reverse Side