

OIL CONSERVATION DIVISION

RECEIVED 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-77

FEB 03 1981

O. C. D.

5a. Indicate Type of Lease

State ☐Fee ☒

5. State Oil & Gas Lease No.

SUNDY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

ALL ☒GAS WELL ☐

OTHER-

Name of Operator

Yates Petroleum Corporation ✓

7. Unit Agreement Name

8. Farm or Lease Name

Jackson Estate BY

9. Well No.

14

10. Field and Pool, or Wildcat
Eagle Creek SAUNIT LETTER K 1650 FEET FROM THE South LINE AND 1650 FEET FROMWest LINE, SECTION 22 TOWNSHIP 17S RANGE 25E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)

3540' GR

12. County

Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
PARTIALLY ABANDON ☐
ALTER CASING ☐PLUG AND ABANDON ☐
CHANGE PLANS ☐REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☒
OTHER ☐ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spudded a 15" hole at 2:15 PM 1-29-81.

361' Ran 9 joints of 10-3/4" 40.50# K-55 ST&C casing set at 361'. 1-regular pattern guide shoe at 361'. Flapper float insert at 322'. Cemented w/250 sacks Class "C" 4% CaCl. PD 8:00 PM 1-29-81. Bumped plug to 800 psi. Circulated 35 sacks cement. WOC 24 hours. Reduced hole to 9-1/2". Drilled plug and resumed drilling.

1155' Ran 29 joints of 7" 20# K-55 ST&C casing set a 1155'. 1-regular pattern guide shoe at 1155'. Flapper insert float at 1116'. Cemented w/400 sacks 65-35 Poz, 4% Bentonite, 8# Kolite, 1/4# celloflakes and 3% CaCl. Tailed in w/150 sacks Class "C" 4% CaCl. PD 1:00 PM 1-31-81. Bumped plug to 900 psi, released pressure and float held okay. Cement circulated 50 sacks to pit. WOC 18 hours. Nipped up and tested to 1500 psi okay. Reduced hole to 6-1/4". Drilled plug and resumed drilling.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

TITLE Engineering Secretary

DATE Feb. 2, 1981

TITLE OIL AND GAS INSPECTOR

DATE FEB 06 1981

SIGNATURES OF APPROVAL, IF ANY: