CNEFIGY AND MINERALS DEPARTMENT	
OIL CONSERVATION DIVIS N DISTRIBUTION SANTA FE I FILE SANTA FE, NEW MEXICO 87501	Farm C-103 Revised 10-1-7;
U.S.G.S. LAND OFFICE	Sa. Indicate Type of Lease State Fee X. S. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS 100 NOT USE THIS FORM FOR PAGPONALS TO DELLE OF TO DEFENS OF PLUS DALA TO A DEFERENT ASSERVOID USE THIS FORM FOR PAGPONALS OF PERMIT - " (FOLL C-101) FOR SUCH PROPONALS.) NECEVED	7, Unit Agreement Name
Yates Petroleum Corporation V	8. Form or Lease Name Jackson Estate BY
Address of Operator O. C. D. 207 South 4th St., Artesia, NM 88210 ARTESIA, OFFICE	9. Well No. 15
UNIT LETTER K 2310 FLET FROM THE SOUTH LINE AND 2310 FEET FROM	10. Field and Post, or Wildcot Eagle Creek SA
THE West LINE, SECTION 22 TOWNSHIP 17S RANGE 25E NUPL.	
15. Elsystion (Show whether DF, RT, GR, etc.) 3542' GR	12. County Eddy
Check opriate Box To Indicate Nature of Notice, Report or Oth NOTICE OF 11 1710N TO: SUBSEQUENT	
PLUG AND ABANDON PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS. CULI OR ALTER CASING COMMENCE DRILLING OPNS. CHANGE PLANT CASING TEST AND CEMENT JQB X	ALTERING CASING
отна	L

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

## Spudded a 15" hole at 2:30 PM 2-14-81.

TD 343' Ran 9 joints of 10-3/4" 40.50# K-55 ST&C casing set at 343'. 1-notched guide shoe at 343'. Flapper insert float at 305'. Cemented w/250 sacks Class C 4% CaCl. PD 11:30 PM 2-14-81. Bumped plug to 500 psi, released pressure and float held okay. Cement circulated 35 sacks to pit. WOC 12 hours. Reduced hole to 9-1/2". Drilled plug and resumed drilling. TD 1168' Ban 29 joints of 7" 20# K 55

TD 1168' Ran 29 joints of 7" 20# K-55 casing set at 1168'. 1-regular pattern guide shoe at 1168'. Flapper float insert at 1127'. Cemented w/400 sacks 65-35 Poz, 8# Kolite, 3% CaCl. 1/4# celloflakes and 4% gel. Tailed in w/150 sacks Class C 3% CaCl. PD 4:00 AM 2-17-81. Bumped plug to 900 psi, released pressure and float held okay. Cement circulated 35 sacks. WOC 18 hours. Nippled up and tested to 1500 psi okay. Reduced hole to 6-1/4".

16. Thereby certify that the information above is true and complet	e to the best of my knowledge and belief.		1994 - Hanne Sann, Charles Handlin, Sanna Maria Sanna Anna Anna Anna Anna Anna Anna An
maillanta Docalett	TILL Engineering Secretary	DATE _	Feb. 25-81
man while Walkan	TITLEOIL AND GAS INSPECTOR	DATE	MAR 0 2 1981

CONDITIONS OF APPROVAL, IF ANVE