

OIL CONSERVATION DIVISION

P. O. BOX 2080

SANTA FE, NEW MEXICO 87501

Form C-101
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.B.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease

State ☐For ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ WELLGAS WELL ☐OTHER ☐

2. Name of Operator

Yates Petroleum Corporation ✓

3. Address of Operator

207 South 4th St., Artesia, NM 88210

4. Location of Well

UNIT LETTER C , 330 FEET FROM THE North LINE AND 2310 FEET FROM West LINE, SECTION 31 TOWNSHIP 16S RANGE 26E NMPM.

7. Unit Agreement Name

8. Farm or Lease Name

Zumwalt PT

9. Well No.

1

10. Field and Pool, or WHCcat

Ind. San Andres

15. Elevation (Show whether DF, RT, GR, etc.)

3421' GR

12. County

Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

REPAIR REMEDIAL WORK ☐TEMPORARILY ABANDON ☐ALTER CASING ☐PLUG AND ABANDON ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐COMMENCE DRILLING OPS. ☐CASING TEST AND CEMENT JOB ☒OTHER ☐ALTERING CASING ☐PLUG AND ABANDONMENT ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spudded a 15" hole at 11:30 AM 1-31-81.

TD 395' Ran 10 joints of 10-3/4" K-55 ST&C casing set 395'. 1-notched guide shoe at 395'. Flapper float insert at 353'. Cemented w/400 sacks Class "C" 4% CaCl. PD 9:30 PM 1-31-81. Bumped plug to 500 psi, released pressure and float held okay. Cement circulated 55 sacks to pit. WOC 12 hours. Reduced hole to 9-1/2". Drilled plug and resumed drilling.

TD 1162' Ran 29 joints of 7" 20# K-55 ST&C casing set at 1162'. Flapper float at 1124'. Cemented w/400 sacks 65-35 Poz; 4% Bentonite, 8# Kolite, 1/4# celloflakes and 3% CaCl. Tailed in w/150 sacks Class "C" 2% CaCl. PD 7:45 PM 2-2-81. Bumped plug to 900 psi, released pressure and float held okay. Cement circulated 45 sacks to pit. WOC 18 hours. Nippled up and tested to 1500#, OK. Reduced hole to 6-1/4"

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signature: Engineering SecretaryTITLE Engineering SecretaryDATE Feb. 9, 1981APPROVED BY: Mike WilliamsTITLE Oil and Gas InspectorDATE FEB 12 1981

COMPLETION OF APPROVAL, IF ANY: