| NERGY AND MINERALS DEPARTMEN | | SERVA | TION DIVISION. | | |
|--|--|------------|---|-----------|--|
| DISTRIBUTION | | | | | Form C-103 |
| SANTA FE | P. O. BOX 2088 SANTA FE, NEW MEXICO 87501 | | | | Revised 10-1-78 |
| FILE | SANTA | FE, NEW | MEXICO 87501 | | |
| U.S.G.S. | | | | | 5a. Indicate Type of Leuse |
| LAND OFFICE | | | | | State 🗶 🛛 🖌 Fee |
| OPERATOR / | | | | | 5. State Oil 6 Gas Lease No. |
| | | | | | B - 161 - 3 |
| SUNDRY DO NOT USE THIS FORM FOR PROPE USE "APPLICATION | NOTICES AND RE | PORTS ON | | ÆÐ | |
| | отнел- | | MAY 2.9 | 1981 | 7. Unit Agreement Name |
| Name of Operator | | | | 1001 | 8. Furm or Lease Name |
| Anadarko Production Co | mpany 🗸 | | | • | Brinson |
| Address of Operator | | | | | 9. Well No. |
| P. 0. Box 67, Loco Hil | ls, New Mexico | 88255 | stat 12 sy Cr | 11.11 | 4 |
| Location of Well | | | | | 10. Field and Pool, or Wildcat Grayburg-Jackson-Seven |
| UNIT LETTER H | 0 FEET PROM THE | North | LINE AND 990 | FEET FROM | Grayburg-Jackson-Seven Rivers-Queen-Grayburg-SA |
| THE East LINE, SECTION | 36 TOWNS | 165 | 31E | | |
| 15. Elevation (Show whether DF, RT, GR, etc.) | | | | | 12. County |
| 111/11/11/11/11/11/11/11/11/11/11/11/11 | | | | | Eddy |
| Check A | | | | | |
| | ppropriate Box 10 | Indicate N | ature of Notice, Repo | | |
| NOTICE OF INT | ENTION TO: | | SUBS | EQUENT | REPORT OF: |
| RFORM REMEDIAL WORK | PLUG A.D A | | REMEDIAL WORK | | ALTERING CASING |
| LL OR ALTER CASING | | | COMMENCE DRILLING OPNS. | h | PLUS AND ABANDONMENT |
| | CHANGE PL | ^*** [] | CASING TEST AND CEMENT JO DTHER Progress | | |
| | | | OTHER LUGIESS | Report | X |
| | • | | | | |
| 01/6# | • | L_ | | | |

- Rigged up rotary tools; spudded 125 note @ 0745 PH 5-0-81.
 Drilled to 465' with full circulation; ran 8-5/8" casing with casing shoe @ 457' KB & cemented with 350 sx Class H with 2% CaCL, circulated 100 sx to pit. PD @ 9:15 PM 5-7-81. Installed Series 900 Double Ram Hydraulic Blowout Preventor, tested to 1000# psi.
- 3. WOC 12 hours prior to drilling shoe on surface casing with 7-7/8" bit. Drilled to 4028' KB; ran Open Hole logs.
- 4. Ran 5½" casing with casing shoe @ 4027 KB; Halliburton cemented with 500 sx Halliburton Lite with 5# Gilsonite/sx, ½# Flocele/sx, 8# Salt/sx & tailed in with 250 sx Class H with .5 of 1% CFR-2 and 10# No. 3 sand/sx.
- 5. Displaced cement with 22 bbls of fresh water behind plug. Cement plug stopped @ 1430'. Pressured to 2000# could not move plug. This left 1390' of 5½" casing from 1430' to 4020' (TD) full of Class H cement. The Halliburton Lite should be behind the 5½" casing (in OH) from 4020' (TD) up to 2100' (calculated cement top = 2100').
- 6. Rigged up pulling unit.
- 7. Drilled cement from 1430' 1800' as of the morning of 5-21-81.

<u>Note</u>: Plan to drill cement to TD; run Cement Bond log to determine actual cement top; Perforate @ cement top & circulate cement to surface outside $5\frac{1}{2}$ " casing prior to completion.

| 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. | | | | | | | | | |
|--|--------|----------------------------|------|--------------|--|--|--|--|--|
| one Chine Cuches | TITLE_ | Area Supervisor | DATE | May 21, 1981 | | | | | |
| For Record Only | 7176.6 | SUPERVISOR, DISTRICT II | · | MAY 2 6 1981 | | | | | |
| | - | no 18 hrs. or see Fule 107 | | | | | | | |