

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other

2. NAME OF OPERATOR
HUSKY OIL COMPANY

3. ADDRESS OF OPERATOR
600 S. Cherry St., Denver, CO 80222

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 660' FNL & 1980' FWL, NE NW
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:	SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF <input type="checkbox"/>	<input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE <input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES <input type="checkbox"/>	<input type="checkbox"/>
ABANDON* <input type="checkbox"/>	<input type="checkbox"/>
(other) <u>Ran Intermediate Casing</u>	

5. LEASE

NM 17215

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Husky Federal

9. WELL NO.

2

10. FIELD OR WILDCAT NAME

1. A. Diamond Mound, Atoka

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 15-16S-27E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

14. API NO.

30-015-23731

15. ELEVATIONS (SHOW DF, KDB, AND-WD)

3568' GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Ran 38 jts, 8-5/8", 24#, J-55, ST&C csg. Set @ 1500' KB.

Cmtd w/475 sx Pacesetter Light + 8% salt + 10 pps Gilsonite + 1/4 pps Celloseal.
Tailed in w/200 sx Class "C" + 8% salt + 10 pps Gilsonite.

Had 10 bbls cmt returns to surface. CIP @ 12:10 a.m. 7/3/81

RECEIVED
JUL 10 1981

Subsurface Safety Valve: Manu. and Type

18. I hereby certify that the foregoing is true and correct

SIGNED

Roger A. Chapman

TITLE

Engr. Assistant

DATE

July 8, 1981

APPROVED BY
CONDITIONS OF

ACCEPTED FOR RECORD
ROGER A. CHAPMAN

TITLE

DATE

APPROVAL, IF ANY:

JUL 13 1981

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

*See Instructions on Reverse Side

OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

Ft.