

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ well gas ☐ well other

2. NAME OF OPERATOR

RPM Energy, Inc. ✓

3. ADDRESS OF OPERATOR

613 Commercial Bank Tower, Midland, TX 79701

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 430' FNL, 2210' FEL

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☐

(other) Well Report ☐

☐

☐

☐

☐

☐

☐

☐

☐

☐

☒

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

12/12/81	2.78 BO	25 bbls wtr
12/13/81	2.78 BO	25 bbls wtr
12/14/81	1.39 BO	15 bbls wtr
12/15/81	0 BO	15 bbls wtr
12/16/81	1.16 BO	20 bbls wtr
12/17/81	1.16 BO	18 bbls wtr
12/18/81	1.39 BO	16 bbls wtr
12/19/81	1.39 BO	15 bbls wtr
12/20/81	1 BO	13 bbls wtr
12/21/81	1.48 BO	12 bbls wtr
12/22/81	1.16 BO	16 bbls wtr
12/23/81	0 BO	13 bbls wtr

12/24/81	.5 BO	11 bbls wtr
12/25/81	1.16 BO	8 bbls wtr
12/26/81	1.48 BO	12 bbls wtr
12/27/81	0 BO	15 bbls wtr
12/28/81	.75 BO	11 bbls wtr
12/29/81	1.75 BO	7 bbls wtr
12/30/81	1 BO	7.5 bbls wtr
12/31/81	.32 BO	7 bbls wtr
1/1/82	1.16 BO	5 bbls wtr
1/2/82	1.48 BO	6 bbls wtr
1/3/82	1.75 BO	3 bbls wtr

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Bella Dean TITLE Prod. Secretary DATE _____

ACCEPTED FOR RECORD
ROGER A. CHAPMAN

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF

FEB 1 1982

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

See Instructions on Reverse Side

RECEIVED
JAN 27 1982
OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

5. LEASE
NM 14297-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME RECEIVED

8. FARM OR LEASE NAME FEB 24 1982
CITCO Federal

9. WELL NO. O. C. D.
1

10. FIELD OR WILDCAT NAME ARTESIA, OFFICE
Undesignated San Andres

11. SEC., T., R., M., OR BLK. AND SURVEY OR
AREA

Sec. 21, T-16-S, R-26-E

12. COUNTY OR PARISH Eddy 13. STATE NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
3355 GL

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Artesia, NM 88210

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ gas ☐ other2. NAME OF OPERATOR
RPM Energy, Inc.3. ADDRESS OF OPERATOR
613 Commercial Bank Tower, Midland, TX 797014. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 430' FNL, 2210' FEL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) Well Report

SUBSEQUENT REPORT OF:

☐
☐
☐
☐
☐
☐
☐
☐
☒

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1/4/82	.64 BO	4.16 bbls wtr	1/16/82	1.16 BO	1.16 bbls wtr
1/5/82	.96 BO	4.78 bbls wtr	1/17/82	1 BO	1.16 bbls wtr
1/6/82	1.28 BO	3.64 bbls wtr	1/18/82	.5 BO	1.48 bbls wtr
1/7/82	1 BO	2.48 bbls wtr	1/19/82	.32 BO	.96 bbls wtr
1/8/82	1.16 BO	2 bbls wtr	1/20/82	1 BO	1.16 bbls wtr
1/9/82	1 BO	1 bbl wtr	1/21/82	1.16 BO	1.48 bbls wtr
1/10/82	.5 BO	1 bbl wtr	1/22/82	.5 BO	1 bbls wtr
1/11/82	.96 BO	1.48 bbls wtr	1/23/82	.96 BO	1.16 bbls wtr
1/12/82	1.16 BO	2 bbls wtr	1/24/82	1 BO	1 bbls wtr
1/13/82	1.5 BO	1.96 bbls wtr	1/25/82	1 BO	2.48 bbls wtr
1/14/82	1 BO	1 bbl wtr			
1/15/82	.5 BO	1.16 bbls wtr			

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.


18. I hereby certify that the foregoing is true and correct

SIGNED Becki Dean TITLE Prod. Secretary DATE 1/25/82

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____



UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ well gas ☐ well other

2. NAME OF OPERATOR
RPM Energy, Inc.

3. ADDRESS OF OPERATOR
613 Commercial Bank Tower, Midland, TX 79701

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 430' FNL, 2210' FEL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) Well Report ☐

SUBSEQUENT REPORT OF:

☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☒

RECEIVED
DEC 14 1981

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

5. LEASE
NM 14297-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
CITCO Federal DEC

9. WELL NO.
1 O. C. D.

10. FIELD OR WILDCAT NAME
Undesignated San Andres ARTESIA, OFFICE

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 21, T-16-S, R-26-E

12. COUNTY OR PARISH
Eddy

13. STATE
NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
3355 GL

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

12/3/81	25 bbls wtr	1 BO
12/4/81	30 bbls wtr	1 BO
12/5/81	27 bbls wtr	1 BO
12/6/81	30 bbls wtr	1 BO
12/7/81	Well dn	
12/8/81	SD-bearing is out	
12/9/81	SD-bearing is out	
12/10/81	6.98 bbls fluid. Working on gas engine.	
12/11/81	Set new engine; started it @ 10:00 a.m.	

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Buckie C. Dean TITLE Prod. Secretary DATE 12/11/81

APPROVED BY JOHN A. CHAPMAN
CONDITIONS OF APPROVAL, IF ANY:

(This space for Federal or State office use)

TITLE _____ DATE _____

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

*See Instructions on Reverse Side