

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

C/SF  
**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ gas ☐ other ☒

2. NAME OF OPERATOR  
RPM Energy, Inc.

3. ADDRESS OF OPERATOR  
613 Commercial Bank Tower, Midland, TX 79701

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 330' FNL, 380' <sup>E</sup>FNL  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>		<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>		<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>		<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>		<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>		<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>		<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>		<input type="checkbox"/>
ABANDON* Well Report	<input type="checkbox"/>		<input type="checkbox"/>
(other)			

5. LEASE  
NM 14297-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME RECEIVED

8. FARM OR LEASE NAME  
CITCO Federal DEC 14 1981

9. WELL NO.  
2-Y O. C. D.

10. FIELD OR WILDCAT NAME ARTESIA, OFFICE  
Undesignated San Andres

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Sec. 21, T-16-S, R-26-E

12. COUNTY OR PARISH Eddy 13. STATE  
New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)  
3356 GL

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

11/19/81 SI RIH w/pmp & rods as follows: 1 each 2"x1½"x8' pmp w/strainer, 1 each 2' sub, 47 jts 5/8" rods 1 each 8' sub, PR/ lin. Seated pmp, clamped well off, RD & MO.

11/20/81 Set pmp un & WO engine.

11/21/81 WO mot.

11/22/81 SI. WO mot.

11/23/81 SI. WO mot.

11/24/81 Put well to pmpg. Engine blew valve. Dn for repairs.

11/25/81 30 bbls wtr.

11/26 thru 11/29 30 bbls wtr daily

11/30 thru 12/1 30 bbls wtr-SSO

12/2/81 Gas locked. 10 bbls wtr-no oil

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Beckie Dean TITLE Prod. Secretary DATE 12-4-81

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ gas ☐ other ☐  
well well  
2. NAME OF OPERATOR  
RPM Energy, Inc.  
3. ADDRESS OF OPERATOR  
613 Commercial Bank Tower, Midland, TX 79701  
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 330' FNL, 380' FNL  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:	SEQUENT REPORT OF:
TEST WATER SHUT-OFF <input type="checkbox"/>	<input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE <input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES <input type="checkbox"/>	<input type="checkbox"/>
ABANDON* <input type="checkbox"/>	<input type="checkbox"/>
(other) Well Report	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

11/15/81 thru 11/16/81 SI for weekend  
11/17/81 Flowing to pit. Frac job: 10,000 gal west-pad "A" mix 10# brine, (Summary) 40,000 gal. polaris 30, 10,000# 100 mesh salt. 37,000# 20-40 sd, pmp 25 BPM, 4,500# Max P. Actual frac job--5,000 gal. pad west-pad "A", 5,000 gal. pad west - pad "A" with 2#/gal. 1,000 mesh salt, (Detail) 6,000 polaris pad 4,000 gal pad with 1/2#/gal. 20-40 sd. 10,000 polaris pad 1 1/2#/gal. 20-40 sd. 10,000 polaris pad with 2#/gal. 20-40 sd. Flush perfs.  
11/18/81 Prep to run rods. Remarks: Well died. MIRU PU. RIH w/tbg opn ended. Ran to 1340'. No sd fill. Pld to 1242'. Swbd well. Recd approx 30 bbls wtr-trace of oil-some gas-no sd. POH W/tbg. Went in hole w/prod string: BP; perf nip; SN; 38 jts tbg to sfc. Flgd well up. SION. End of tbg @ 1242'. SN at 1208'. Recd tot after frac: 60 bbls wtr, 1 bbl oil, SSG.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Reclie Dean TITLE Prod. Secretary DATE 12-4-81

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ well ☐ gas well ☐ other ☐  
2. NAME OF OPERATOR  
RPM Energy, Inc. ✓  
3. ADDRESS OF OPERATOR  
613 Commercial Bank Tower, Midland, TX 79701  
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 330' FNL, 380' <sup>E</sup> FNL  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
CHANGE ZONES ☐  
ABANDON\* ☐  
(other) Well Report ☐

SUBSEQUENT REPORT OF:

RECEIVED  
DEC 07 1981  
OIL & GAS  
U.S. GEOLOGICAL SURVEY  
ROSWELL, NEW MEXICO

5. LEASE  
NM 14297-A  
6. IF INDIAN, ALLOTTEE OR TRIBE NAME  
7. UNIT AGREEMENT NAME RECEIVED  
8. FARM OR LEASE NAME  
CITCO Federal DEC 14 1981  
9. WELL NO.  
2-Y O. C. D.  
10. FIELD OR WILDCAT NAME ARTESIA, OFFICE  
Undesignated San Andres  
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Sec. 21, T-16-S, R-26-E  
12. COUNTY OR PARISH Eddy 13. STATE  
New Mexico  
14. API NO.  
15. ELEVATIONS (SHOW DF, KDB, AND WD)  
3356 GL

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

11/7/81 thru 11/10/81 WOCU  
11/11/81 Presently SI. RU CRC WL. Ran SBL, GR & CCL. Bond log O.K. Perf w/ select fire csg gun as follows: 1211', 1216', 1226', 1232½', 1236', 1238½', 1241', 1247', 1253', 1262', 1266', 1276', 1280', 1283', 1288'. 15 shots.  
11/12/81 Prep to ac. MIRU PU. Run in hole w/tbg & pkr. SI.  
11/13/81 SI. Remarks: RU Dresser Titan. A/4000 gal 15% NEFE ac. Broke @ 2200#. Pmp 4 BPM. Drpd 2 balls every 6 bbls. Balled out. Surged balls & continued to pmp 6 bbls a min @ 2200 lbs. Flush w/kcl. ISDP 1100 lbs. 5 min 900#. 10 min 850#. RD & MO  
11/14/81 SI at report time. RU Western; frac well, pmpd in @ 3200# @ 25 BPM. Max P 3300#, Min P 2550#, Avg P 3200# @ 25 BPM. ISDP 800#; 5 min 700#; 15 min. 700#; 30 min. 700#.

Subsurface Safety Valve: Manu. and Type

Set @ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Richard C. Dean

TITLE Prod. Secretary DATE 12-4-81

DEC 11 1981

(This space for Federal or State office use)

APPROVED BY  
CONDITIONS OF APPROVAL  
U.S. GEOLOGICAL SURVEY  
ROSWELL, NEW MEXICO

TITLE DATE