

County ... Eddy

Company ... OXY ... U.S.A., Inc.

Lease ... Bedingfield #1

. 330 ft. from ... N ... line & . 330 ft. from ... W ... line

Ut ... D ... , Sec. 22 ... , Twp. 16 ... , Rge. 26 ... ,

Condition ... P & A ... 12-28-89

... Sub. Report 5-7-90

... 2 - joints at tubing

... Trash - no Pvt Marker

... cello needs filling in

water around ^{pipe} casing -

~~casing~~ ~~base~~ 13 3/8 casing -

8 5/8 not there 7/17/90

DLW