

DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE  
(Other instructions on reverse side)

Form No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Beach Exploration, Inc.		8. FARM OR LEASE NAME Ryan Federal	
3. ADDRESS OF OPERATOR 800 N. Marienfeld Ste. 200 Midland, Texas 79701		9. WELL NO. 2	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1780' FNL & 660' FEL, Unit H SE/4 NE/4.		10. FIELD AND POOL, OR WILDCAT High Lonesome (Queen)	
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OF AREA Sec. 19 T16S, R29E	
15. ELEVATIONS (Show whether DF, RT, GR, etc.)		12. COUNTY OR PARISH Eddy	
		13. STATE NM	

DEC 12 '96

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETION	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		<input type="checkbox"/>

SUBSEQUENT REPORT OF:


WATER SHUT-OFF	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREATMENT	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOTING OR ACIDIZING	<input type="checkbox"/>	ABANDONMENT*	<input checked="" type="checkbox"/>
(Other)	<input type="checkbox"/>		<input type="checkbox"/>

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

11-26-96 Rig up pulling unit, ran in hole with scraper to 1679', set retrievable bridge plug @1641', pressured up and ran test to 500# for 30 minutes. Casing OK. Pulled out of hole with tubing, installed 5 1/2" X 2" swage and 2" valve. Shut well in. RDMO

Beach Exploration, Inc. respectfully request approval for Temporarily Abandonment on the Ryan Federal. BLM was contacted prior to test 11-25-96 and morning of 11-26-96.

SEE ATTACHED FOR  
CONDITIONS OF APPROVAL



18. I hereby certify that the foregoing is true and correct

SIGNED Alexis C. Swoboda TITLE Production DATE 12-2-96

(This space for Federal or State office use)

APPROVED BY (ORIG. SGD.) ALEXIS C. SWOBODA TITLE PETROLEUM ENGINEER DATE DEC 11 1996

CONDITIONS OF APPROVAL, IF ANY: APPROVED FOR 6 MONTH PERIOD

ENDING 6/11/97

See Instructions on Reverse Side

60 PRINTED IN U.S.A. 60

DAY

NIGHT

