

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug a well to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ well gas ☐ well other ☐ **OIL & GAS**
MINERALS MGMT. SERVICE
2. NAME OF OPERATOR **ROSWELL, NEW MEXICO**
Yates Petroleum Corporation
3. ADDRESS OF OPERATOR
207 South 4th St., Artesia, NM 88210
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 990 FSL & 330 FEL, Sec. 21-17S-25E
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF ☐ ☐
FRACTURE TREAT ☐ ☒
SHOOT OR ACIDIZE ☐ ☒
REPAIR WELL ☐ ☐
PULL OR ALTER CASING ☐ ☐
MULTIPLE COMPLETE ☐ ☐
CHANGE ZONES ☐ ☐
ABANDON* ☐ ☐
(other) Production Casing

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TD 1500'. Ran 38 jts of 4-1/2" J-55 ST&C casing set at 1473'. 1-Flapper float shoe set at 1473'. Cemented w/200 sacks 1:2 Talc & .2% TF-4, .4% CF-2 and 1% CaCl with .2% AFC. Compressive strength of cement - 1050 psi in 12 hrs. PD 12:15 PM 10-12-82. Bumped plug to 1000 psi, released pressure and float held okay. WOC 18 hrs. WIH and perforated in 2 stages. Stage 1: 1274-1465 w/13 .50" holes as follows: 1274, 83, 91, 98, 1304, 22, 29, 60, 67, 73, 94, 99 & 1465'. Stage 2: 1279-1459' w/17 .50" holes as follows: 1279, 87, 95, 1301, 14, 18, 26, 33, 51, 57, 64, 70, 77, 91, 96, 1451 & 59'. Frac'd well (via casing) with 60000 gallons gelled 1% KCL water with 120000# (110000# 20/40 sd + 10000# 100 mesh) sand, 2000 gallons 15% NEA HCL acid. Set pumping equipment. Begin pumping back load.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED David R. Glass TITLE Engineering Secty DATE 10-27-82

ACCEPTED FOR RECORD

(ORIG. SGD.) DAVID R. GLASS

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL _____

NOV 9 1982
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

*See Instructions on Reverse Side

5. LEASE NM 0219603
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME Federal BZ
9. WELL NO. 18
10. FIELD OR WILDCAT NAME O. C. D.
Eagle Creek SAARTESIA, OFFICE
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Unit P, Sec. 21-T17S-R25E
12. COUNTY OR PARISH Eddy 13. STATE NM
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
3551' GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)