

NM OIL CONS. COMMISS
Drawer DD
Artesia, NM 88210

Form Approved.
Budget Bureau No. 42-R1424

c/sf

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☒ gas well ☐ other ☐
2. NAME OF OPERATOR
Yates Petroleum Corporation ✓
3. ADDRESS OF OPERATOR
207 South 4th St., Artesia, NM 88210
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 990 FNL & 990 FEL, Sec. 28-17S-25E
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:
TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

SUBSEQUENT REPORT OF:

☒
☐
☐
☐
☐
☐
☐
☐
☐
☐

5. LEASE
NM 0219603
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Federal BZ
9. WELL NO.
22
10. FIELD OR WILDCAT NAME
Eagle Creek SA
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Unit A, Sec. 28-T17S-R25E
12. COUNTY OR PARISH
Eddy
13. STATE
NM
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
3555' GR

RECEIVED

JAN 24 1983

O. C. D.
ARTESIA, OFFICE

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

MINERALS MGMT. SERVICE
ROSWELL, NEW MEXICO

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded a 14-3/4" hole at 10:30 AM 1-4-83.

Ran 8 joints of 10-3/4" 40.5# casing set at 320'. 1-Texas Pattern notched guide shoe set at 320'. Insert float at 280'. Cemented w/225 sacks Class "C" 3% CaCl₂. Compressive strength of cement - 1275 psi in 12 hours. PD 6:45 AM 1-4-83. Bumped plug to 750 psi, released pressure and float held okay. Cement circulated 30 sacks. WOC. Drilled out 6:45 AM 1-5-83. WOC 12 hours. Cut off and welded on flow nipple. Reduced hole to 7-7/8". Drilled plug and resumed drilling.

Subsurface Safety Valve: Manu. and Type

Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED _____ Production Supervisor DATE 1-12-83
TITLE _____

ACCEPTED FOR RECORD (This space for Federal or State office use)

APPROVED BY (ORIG. SGD.) DAVID R. GLASS DATE _____
CONDITIONS OF APPROVAL IF ANY

JAN 21 1983
MINERALS MANAGEMENT SERVICE
ROSWELL, NEW MEXICO

*See Instructions on Reverse Side