

NEW MEXICO OIL CONSERVATION COMMISSION  
DRAWER DD  
ARTESIA, NEW MEXICO

FIELD REPORT FOR CEMENTING OF WELLS

|                                 |                         |                          |                                 |                 |                    |
|---------------------------------|-------------------------|--------------------------|---------------------------------|-----------------|--------------------|
| Operator <u>Wes. Pet. Corp.</u> |                         | Lease <u>Johnson FE.</u> |                                 | Well # <u>4</u> |                    |
| Location of Well                | Unit <u>990N 990E A</u> | Section <u>23</u>        | Township <u>17</u>              | Range <u>2S</u> | County <u>Eddy</u> |
| Drilling Contractor             | <u>AFT #1</u>           |                          | Type of Equipment <u>Rotary</u> |                 |                    |

\*witness

APPROVED CASING PROGRAM

| Size of Hole | Size of Casing | Weight Per Foot | New or Used | Depth | Sacks Cement |
|--------------|----------------|-----------------|-------------|-------|--------------|
| 14 1/2       | 10 3/4"        | 30#             |             | 400   | Circ         |
| 9 1/2        | 7"             | 23#             |             | 1150  | Circ         |
| 6 1/4        | 4 1/2"         | 9.5#            |             | 1500  | Circ         |

Casing Data:

Surface \_\_\_\_\_ joints of \_\_\_\_\_ inch \_\_\_\_\_ # Grade \_\_\_\_\_

(Approved) (Rejected) \_\_\_\_\_

Inspected by \_\_\_\_\_ date \_\_\_\_\_

Cementing Program

Size of hole 9 1/2" Size of Casing 7" Sacks cement required \_\_\_\_\_

Type of Shoe used guide Float collar used insert Btm 3 jts welded yes

TD of hole 1203' Set 1203' Feet of 7" Inch 20 # Grade J-55

New-used csg. @ 1203' with 175sx C Sacks neat cement around shoe + 225 sax pacasette lite additives (1/4# closed, 10# gilsonite, 370cc)

Plug down @ 8:00 pm (AM) (PM) Date 3/31/83

Cement circulated No No. of Sacks -0-

Cemented by Western Co. Witnessed by Mike Stubbfield

Temp. Survey ran @ 10:30 (AM) (PM) Date 4/1/83 top cement @ \_\_\_\_\_

Casing test @ \_\_\_\_\_ (AM) (PM) Date \_\_\_\_\_

Method Used \_\_\_\_\_ Witnessed by \_\_\_\_\_

Checked for shut off @ \_\_\_\_\_ (AM) (PM) Date \_\_\_\_\_

Method used \_\_\_\_\_ Witnessed by \_\_\_\_\_

Remarks: While pumping displacement plug cement bridged off on backside. Pumped 22 BBL Displacement.

lost circ. @ 220'

lost 1/2 inch @

No centralizers or baskets

TAGGED AT 544' COULD NOT WK. BY CAVINGS PUMPED 100 SXS. C.I.C 3% CaCl<sub>2</sub> WOL 3HRS. TAGGED AT 330' PUMPED 100 SXS. B.I.C. 3% CaCl<sub>2</sub> circ. 5 SXS. to the pit.