

CSF

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well  gas well  other  **JUL 13 1983**

2. NAME OF OPERATOR **O. C. D.**  
C.E. LaRue and B.N. Muncy, Jr. **ARTESIA, OFFICE**

3. ADDRESS OF OPERATOR  
P.O. Box 196, Artesia, NM 88210

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 2310' FNL & 425' FEL Section 15, T16S, R31E  
AT SURFACE:  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:

5. LEASE  
NM 18230

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME  
Read & Stevens

9. WELL NO.  
1

10. FIELD OR WILDCAT NAME **2-32**  
**Square Lake North (Undesignated)**

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Section 15, T16S, R31E

12. COUNTY OR PARISH | 13. STATE  
Eddy | NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)  
4231.5 GL

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:	SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF <input type="checkbox"/>	<input checked="" type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE <input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES <input type="checkbox"/>	<input type="checkbox"/>
ABANDON* <input type="checkbox"/>	<input type="checkbox"/>
(other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Ran 1068' of 8 5/8" API 24# Casing, circulated cement with 550 sacks.  
Waited 18 hrs. on cement, tested to 800# with no leakage. 4/30/83.

**RECEIVED**

MAY 11 1983

OIL & GAS

ROSWELL, NEW MEXICO

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Operator DATE May 2, 1983

ACCEPTED FOR RECORD (space for Federal or State office use)  
**(ORIG. SGD.) DAVID R. GLASS**

APPROVED BY \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:  
**JUL 14 1983**

ROSWELL, NEW MEXICO

\*See Instructions on Reverse Side