

**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ gas ☐  
well well other

2. NAME OF OPERATOR  
Yates Petroleum Corporation

3. ADDRESS OF OPERATOR  
207 South 4th St., Artesia, NM 88210

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 1650 FNL & 1650 FEL, Sec.28-17S-25E  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
CHANGE ZONES ☐  
ABANDON\* ☐  
(other) ☐

☒  
☐  
☐  
☐  
☐  
☐  
☐  
☐

5. LEASE

NM 021963

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME RECEIVED BY

8. FARM OR LEASE NAME  
Federal BZ

AUG 29 1983

9. WELL NO.  
24

O. C. D.  
ARTESIA, OFFICE

10. FIELD OR WILDCAT NAME  
Eagle Creek SA

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Unit G, Sec. 28-T17S-R25E

12. COUNTY OR PARISH

Eddy

13. STATE

NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)  
3557' GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

RECEIVED  
AUG 17 11 18 AM '83  
BUREAU OF LAND MANAGEMENT  
ROSWELL DISTRICT

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Spudded 14-3/4" hole 11:30 AM 8-13-83. Ran 8 jts 10-3/4" 40.5# J-55 casing set 332'. 1-Texas Pattern notched guide shoe set 332'. Insert float set 294'. Cemented w/200 sacks Class C 3% CaCl2. Compressive strength of cement - 1250 psi in 12 hours. PD 4:30 PM 8-13-83. Bumped plug to 1000 psi, released pressure and float held okay. Cement did not circulate. WOC 6 hours. Ran Temperature Survey and found top of cement 50'. Ran 1". Tagged cement 57'. Spotted 50 sacks Class C Neat. PD 8:00 PM 8-13-83. Cement circulated 5 sacks. WOC. Drilled out 4:30 AM 8-14-83. WOC 12 hours. Cut off and welded on flow nipple. Reduced hole to 9-7/8". Drilled plug and resumed drilling.

Subsurface Safety Valve: Manu. and Type

Set @ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Production  
Supervisor

DATE

8-15-83

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: