

Drawer D
Artesia, NM 88210

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

RECEIVED BY

JAN 12 1984

O. C. D.

ARTESIA, OFFICE

Form Approved.
Budget Bureau No. 42-R1424

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☒ gas well ☐ other

2. NAME OF OPERATOR

Yates Petroleum Corporation

3. ADDRESS OF OPERATOR

207 South 4th St., Artesia, NM 88210

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 990 FSL & 330 FEL, Sec. 29-17S-25E

AT SURFACE:

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☐

(other) ☐

SUBSEQUENT REPORT OF:

☒

☐

☐

☐

☐

☐

☐

☐

☐

5. LEASE

NM 12832

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal CD

9. WELL NO.

8

10. FIELD OR WILDCAT NAME

Eagle Creek SA

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Unit P, Sec. 29-T17S-R25E

12. COUNTY OR PARISH

Eddy

13. STATE

NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

3588' GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

RECEIVED
JAN 9 10 38 AM '84
BUREAU OF LAND MANAGEMENT
ROSWELL DISTRICT

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded 14-3/4" hole 1:00 PM 1-2-84. Ran 8 jts of 10-3/4" 40.5# J-55 casing set 343'. 1-Texas Pattern notched guide shoe set 343'. Insert float set 300'. Cemented w/225 sacks Class C 2% CaCl2. Compressive strength of cement - 1250 psi in 12 hrs. PD 12:30 AM 1-3-84. Bumped plug to 1000 psi, released pressure and float held okay. Cement circulated 15 sacks. WOC. Drilled out 4:15 PM 1-4-84. WOC 39 hours and 45 minutes. Cut off and welded on flow nipple. Tested casing to 1000 psi for 30 minutes, OK. Reduced hole to 9-7/8". Drilled plug and resumed drilling.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Janita Goodlett TITLE Production Supervisor

DATE 1-5-84

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____

CONDITIONS OF APPROVAL, IF ANY:

DATE

ACCEPTED FOR RECORD

JAN 10 1984