

C/S 77

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☒ gas well ☐ other ☐
2. NAME OF OPERATOR
Metex Pipe and Supply
3. ADDRESS OF OPERATOR
2407 Sierra Vista Rd Artesia, N. M. 88210
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) S-4, T-16S, R-31E
AT SURFACE: 1650' FSL & 2310' FEL
AT TOP PROD. INTERVAL: Eddy Co., N. M.
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:	SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF <input type="checkbox"/>	<input checked="" type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE <input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES <input type="checkbox"/>	<input type="checkbox"/>
ABANDON* <input type="checkbox"/>	<input type="checkbox"/>
(other) Surface Casing <input type="checkbox"/>	<input checked="" type="checkbox"/>

5. LEASE
N M 54423
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Ronadero Fed
9. WELL NO.
#1

RECEIVED BY

JUN 04 1984

O. C. D.

ARTESIA, OFFICE

10. FIELD OR WILDCAT NAME
North Squarelake Field 2-2a
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
S-4, T-16S, R-31E
12. COUNTY OR PARISH
Eddy
13. STATE
N. M.
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
4153.0 GL

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Well spudded at 6:15 P M 5-22-84

Ran 8 joints, 327 ft. 9 5/8", 32.4#, H-40 Casing.

Halliburton pumped 176 sacks class "C" cement with 2% Calcium Chloride.

Circulated 15 sacks to the pit with the plug down at 2:30AM, 5-23-84.

Waited 18 hours on cement and tested casing to 2000 PSI for 30 minutes with no leakage.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Martin Murey TITLE Operator DATE May 23, 1984

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____ ACCEPTED FOR RECORD

JUN 1 1984

*See Instructions on Reverse Side

Carlsbad NEW MEXICO