

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-76

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

5a. Indicate Type of Lease

State ☒ Fee ☐

5. State Oil & Gas Lease No.

LG 3374

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - II" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator

Yates Petroleum Corporation

Address of Operator

207 South 4th St., Artesia, NM 88210

Location of Well

UNIT LETTER B 330 FEET FROM THE North LINE AND 2310 FEET FROM

THE East LINE, SECTION 32 TOWNSHIP 16S RANGE 31E N.M.P.M.

7. Unit Agreement Name

8. Farm or Lease Name

Zephyr "ZQ" State

9. Well No.

1

10. Field and Pool, or Wildcat

Square Lake Grbg-SA

15. Elevation (Show whether DF, RT, GR, etc.)

3948' GR

12. County

Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐

TEMPORARILY ABANDON ☐

PULL OR ALTER CASING ☐

OTHER ☐

PLUG AND ABANDON ☐

CHANGE PLANS ☐

REMEDIAL WORK ☐

COMMENCE DRILLING OPNS. ☒

CASING TEST AND CEMENT JOB ☒

OTHER ☐

ALTERING CASING ☐

PLUG AND ABANDONMENT ☐

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spudded 17-1/2" hole at 6:00 PM 10-3-84. Ran 11 joints of 13-3/8" 54.50# J-55 casing set 448'. 1-Texas Pattern notched guide shoe set 448'. Regular insert float set 410'. Cemented w/375 sacks Class "C" w/2% CaCl2. Compressive strength of cement - 1250 psi in 12 hrs. PD 10:30 AM 10-4-84. Bumped plug to 1000 psi, released pressure and float held okay. Cement circulated 35 sacks to pit. WOC. Drilled out 10:30 PM 10-4-84. WOC 12 hrs. *Cut off and welded on flow nipple. Reduced hole to 12-1/4". Drilled plug and resumed drilling.

*Tested to 1000# for 30 minutes, OK.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signature Leslie A. Clements TITLE Production Supervisor

DATE 10-8-84

PROVED BY Original Signed By
Leslie A. Clements
CONDITIONS OF APPROVAL, IF ANY: Supervisor District II

TITLE DATE OCT 12 1984