

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

RECEIVED BY  
FEB 11 1985  
SUNDAY

Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use APPLICATION FOR PERMIT for such proposals.

1. OFFICE  
ARTESIA, OFFICE

5. LEASE DESIGNATION AND SERIAL NO.  
LC 058794-A

6. IF INDIAN, LOTILE OR TRIBE NAME

7. UNIT ACRS ENT NAME

8. FARM OR LEASE NAME  
Levers Federal

9. WELL NO.  
12

10. FIELD AN POOL, OR WILDCAT  
Und.  
Cave Pool G-5A

11. SEC., T., R. M., OR BLK. AND SURVEY OR AREA  
33-T16S-R29E

12. COUNTY OR PARISH  
Eddy

13. STATE  
N.M.

2. NAME OF OPERATOR  
Diamondback Pet. Inc.

3. ADDRESS OF OPERATOR  
P.O. Box 2938 Ruidoso, N.M. 88345

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below)  
At surface  
660 FNL and 660 FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)  
3603 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

| NOTICE OF INTENTION TO: |                          | SUBSEQUENT REPORT OF: |                          |
|-------------------------|--------------------------|-----------------------|--------------------------|
| TEST WATER SHUT-OFF     | <input type="checkbox"/> | PULL OR ALTER CASING  | <input type="checkbox"/> |
| FRACTURE TREAT          | <input type="checkbox"/> | MULTIPLE COMPLETE     | <input type="checkbox"/> |
| SHOOT OR ACIDIZE        | <input type="checkbox"/> | ABANDON*              | <input type="checkbox"/> |
| REPAIR WELL             | <input type="checkbox"/> | CHANGE PLANS          | <input type="checkbox"/> |
| (Other)                 | <input type="checkbox"/> | (Other) spud well     | <input type="checkbox"/> |

(Note: Report results of multiple completion on Well Completion or Recompletion Report as Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1-9-85 Spud 12 1/4" hole @ 8:15 AM TD 254' run 254' 8 5/8" 24# csng cmt w/ 225 sxs class C 2% CaCl<sub>2</sub> Pd @ 2:52 AM.

1-10-85 Cir 45 sxs to pit. woc 18 hrs. Pressure test to 600# held 30 min drill out w/ 7 7/8" bit.

1-16-85 Td 3575 run Dresser CNL/FDC DLL/RXO.

1-17-85 Run 3556' 5 1/2" 15.5# cmt w/ 1350 sxs Dowell 4 5% Nall tailed in w/ 250 sxs Dowell 4 2% CaCl<sub>2</sub> cir 120 sxs to pit pd @ 11:22 pm woc 18 hrs. Pressure test csng to 1000# held 30 min.

18. I hereby certify that the foregoing is true and correct

SIGNED \_\_\_\_\_ TITLE Geologist DATE 1-31-85

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

FEB 8 1985

\*See Instructions on Reverse Side