

**Schlumberger**

**Anadrill**

MDC Operations  
9900 West Interstate 20  
Midland, Texas 79706  
Phone (915) 563-3057  
Fax (915) 563-3059

August 25, 1998

Oil Conservation Division  
District I  
P.O. Box 1960  
Hobbs, New Mexico 88241-1960

Re: OXY USA, Inc.  
Wallace State Com #1  
Section 9, T17S, R27E, Lot F  
Eddy County, New Mexico  
API # 30-025-30240

Enclosed, please find the original and one copy of the survey performed on the referenced well by Anadrill, a division of Schlumberger Technology Corporation. Other information required by your office is as follows:

<u>Name &amp; Title of Surveyor</u>	<u>Drainhole Number</u>	<u>Surveyed Depths</u>	<u>Dates Performed</u>	<u>Type of Survey</u>
John Hawkes MWD I	#01	7810' to 9112'	8/14/98 - 8/20/98	MWD/D&I

A certified plat on which the bottom hole is oriented both to the surface location and to the lease lines ( or unit lines in case of pooling) is attached to the survey report. If any other information is required, please contact the undersigned at the letterhead address and phone number.

Sincerely,



Tom Follis  
MWD Coordinator

Cc: OXY USA, Inc.

Enclosures: 2

RECEIVED  
JAN 14 1964  
U.S. DEPT. OF JUSTICE  
FEDERAL BUREAU OF INVESTIGATION  
WASHINGTON, D.C.

RECEIVED  
JAN 14 1964  
U.S. DEPT. OF JUSTICE  
FEDERAL BUREAU OF INVESTIGATION  
WASHINGTON, D.C.