

YATES PETROLEUM CORPORATION
Logan ASO Federal Com #1
Section 15-T17S-R27E
Eddy County, New Mexico



RESULTS OF DRILL STEM TESTS:

DST #1 6114-6250': TIMES: TO 20"; SI 60"; TO 60"; SI 120"; TO 60". RECOVERY:
135' of water. SAMPLER: .016 cfg, slight trace of oil and 2500 cc water.
PRESSURES: IHP 2933; IFP 51-59; ISIP 223; 2nd FP 69-78; FSIP 466; FFP 89-95;
FHP 2934.