

- C. If the proposed well is non-productive, all rehabilitation and/or vegetation requirements of the Bureau of Land Management and the United States Geological Survey will be complied with and will be accomplished as expeditiously as possible. All pits will be filled and levelled within 300 days after abandonment.

11. TOPOGRAPHY

- A. The wellsite is located in a relatively flat area.
- B. The top soil at the wellsite is sandy.
- C. The vegetation cover at the wellsite is moderately sparse, with prairie grasses, some mesquite bushes, and shinnery oak.
- D. No wildlife was observed but it is likely that deer, rabbits, coyotes, and rodents traverse the area.

OPERATOR'S REPRESENTATIVES


- A. The field representatives responsible for assuring compliance with the approved surface use plan are:

Michael R. Burton
Division Drilling Manager
Santa Fe Snyder Corp.
550 W. Texas, Suite 1330
Midland, Texas 79701
915-686-6616 - office
915-556-7063 - cellular

CERTIFICATION

I hereby certify that I, or persons under my direct supervision, have inspected the proposed drill site and access route, that I am familiar with the conditions which presently exist; that the statements made in this plan are, to the best of my knowledge, true and correct; and that the work associated with the operations proposed herein will be performed by Santa Snyder Corp. and its contractors and subcontractors in conformity with this plan and the terms and conditions under which is approved.

SIGNED this 30th day of May 2000.


James P. (Phil) Stinson
Agent for Santa Fe Snyder Corp.