

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

| |
|---|
| WELL API NO. 30-005-61785 |
| 5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil & Gas Lease No. LG-734 |
| 7. Lease Name or Unit Agreement Name Little Cuevo Unit |
| 8. Well No. 1 |
| 9. Pool name or Wildcat Wildcat |

| | |
|---|-------------------------|
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS) | |
| 1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER | RECEIVED OCD-ARTESIA |
| 2. Name of Operator YATES PETROLEUM CORPORATION | |
| 3. Address of Operator 105 South 4th St., Artesia, NM 88210 | |
| 4. Well Location Unit Letter <u>J</u> : <u>1980</u> Feet From The <u>South</u> Line and <u>1980</u> Feet From The <u>East</u> Line Section <u>20</u> Township <u>17S</u> Range <u>18E</u> NMPM <u>Chaves</u> County | |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 5358' GR | |

| | |
|---|--|
| 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data | |
| NOTICE OF INTENTION TO: | SUBSEQUENT REPORT OF: |
| PERFORM REMEDIAL WORK <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> |
| OTHER: <input type="checkbox"/> | PLUG AND ABANDONMENT <input checked="" type="checkbox"/> |
| | CASING TEST AND CEMENT JOB <input type="checkbox"/> |
| | OTHER: <input type="checkbox"/> |

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1-22-98 - Moving in and rigged up pulling unit. Shut down. NOTE: Notified Gary Williams w/OCD-Artesia of commencing operations. *Post-ID 2 4-10-98 P47*

1-23-98 - Opened well and bled tubing down. Worked packer for 6 hours. Unset packer. POOH with 134 joints of 2-7/8" tubing and packer. TIH with tubing to CIBP at 4480'. Spotted 25 sacks Class C cement at 4480'. POOH 25 stands. Shut well in.

1-24-98 - Opened well up. TIH with tubing and tagged top of cement at 4249'. Circulated hole with mud laden fluid. POOH with tubing. Nippled down BOP and wellhead. Screwed on pull sub. Picked up on casing and removed slips. Worked and stretched casing. Freepoint at 1100'±. Rigged up wireline. TIH and cut 5-1/2" casing at 3119'. POOH with wireline. Worked casing - casing not free. Shut well in.

1-27-98 - Nippled down 5-1/2" casing handling tools. RIH with 2-7/8" tubing open ended to 3169' (50' below 5-1/2" casng, out at 3119'). Spotted 102 sacks Class C cement with 2% CaCl2 at 3169'. Pulled up hole. WOC. TIH with tubing and tagged top of cement at 2685'. POOH. Nippled down BOP, tubing tools and wellhead. Nippled up to pull 5-1/2"

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

CONTINUED ON NEXT PAGE:

SIGNATURE Rusty Klein TITLE Operations Technician DATE Feb. 5, 1998

TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use)
ORIGINAL SIGNED BY TIM W. GUM
DISTRICT II SUPERVISOR


APPROVED BY _____ TITLE _____ DATE 2-11-98

CONDITIONS OF APPROVAL, IF ANY:

YATES PETROLEUM CORPORATION
Little Cuevo Unit #1
Section 20-T17S-R18E
Chaves County, New Mexico

SUNDRY NOTICE CONTINUED:

casing. RIH with wireline. Cut 5-1/2" casing at 1250'. POOH with wireline. Worked casing - casing not free. Nippled down casing tools. Nippled up to run tubing. RIH with tubing. Spot a 15 sack Class C cement plug from 1300-1150'. POOH with tubing. Nippled down tubing tools. Nippled up to pull casing. RIH with wireline and tagged top of cement at 1150'. Pulled up hole and cut 5-1/2" casing at 1104'. POOH with wireline. POOH with 26 joints of 5-1/2" casing. Shut down for night.
1-28-98 - Shut down for rig repair.
1-29-98 - POOH with 124 joints of 5-1/2" casing. Changed out handling tools. RIH with tubing. Loaded hole with mud laden fluid. Spot a 35 sack Class C cement plug at 1150'. POOH. WOC. RIH with tubing and tagged top of cement at 1015'. Pulled up hole and spotted a 25 sack Class C cement plug at surface. Cleaned location and installed regulation abandonment marker. PLUGGED AND ABANDONED - FINAL REPORT.
Plugging completed 1-28-98.



Rusty Klein
Operations Technician
February 5, 1998