



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office New Mexico  
Lease No. NM 015736  
Unit SH

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			
		<u>Plugging</u>	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Pen American December, 19 62

Well No. 1 is located 1580 ft. from N line and 560 ft. from E line of sec. 11

SE 1/4 NE 1/4 Sec. 11 17S 29E NMPM

(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Square Lake Eddy New Mexico

(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3653 ft.

### DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well was plugged April 7, 1961. Halliburton packers were lost at 2300' in 5 1/2" casing. Top of 5 1/2" casing at 1550'. Hole was mudded back to 1975' and 50' cement plug placed in and above 5 1/2" casing. Hole mudded back to 590' and 50' cement plug placed. Hole mudded back to 475' and 50' cement plug placed. Hole mudded to surface and cement plug with marker set at surface.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Kersey & Company

Address P. O. Box 510

Artesia, New Mexico

By Harold Kersey  
Title Owner