

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

C/SF
08.

OIL CONSERVATION DIVISION

2040 South Pacheco
Santa Fe, NM 87505

WELL API NO.

30-015-02964-00-00

5. Indicate Type of Lease

STATE ☐ FEE ☐ BLM ☐

6. State Oil & Gas Lease No.

LC-028785

7. Lease Name or Unit Agreement Name:

SQUARE LAKE 12 UNIT

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☒ Other

2. Name of Operator

WEBB OIL COMPANY

8. Well No.

117

3. Address of Operator

PO. Box 1124, Artesia, N.M. 88211-1124

9. Pool name or Wildcat

SQUARE LAKE

4. Well Location

Unit Letter N : 660 feet from the S line and 1980 feet from the W line

Section

12

Township

17S

Range

29E

NMPM

County

EDDY

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER:

☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER:

Inj. Well MIT

☒

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions : Attach wellbore diagram of proposed completion or recompilation.

ON MAR 28, 2000 This Inj. Well was put on The Failed List. after MIT. We repacked the head AND replaced one 2" nipple on the head AND retested. ON 6-16-00 we pres. up to 300 PSI AND hold for 20 min AFTER TEST PSI WAS 260 PSI - we notified OCA. AND were Directed to press test to 500 PSI AND test. ON 6-18-00 we pres. up to 500 PSI AND held for 35 min AT end of test PSI WAS 360 PSI. we cannot pump into this well AND it is looseing No fluid - Therefore we request monitor status. Thank you.

Enclosed - "Both charts."

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Rodney B. Webb

TITLE owner

DATE 6-26-00

Type or print name

RODNEY B. WEBB

Telephone No. 505-748-2081

(This space for State use)

505-365-6657


APPROVED BY

Michael S. Webb


TITLE Field Rep. II

DATE 6/30/2000

Conditions of approval, if any:



GRAPHIC CONTROLS CORPORATION
BUFFALO, NEW YORK
Square Lake Unit
117
webb oil G.
G-16 - 2000
BR BC-1500-E



GRAPHIC CONTROLS CORPORATION
BUFFALO, NEW YORK

WCB0076
CHART NO. MC MP-1000

SQ. LAKE 12
117 unit

METER

35 MIN

CHART PUT ON

TAKEN OFF

LOCATION

REMARKS CAWNET Pump Into
6-18-60