

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY Continental Oil Company, Box 427, Hobbs, N. M.
(Address)

LEASE State S-19 WELL NO. 1 UNIT J S 19 T 17 R 29

DATE WORK PERFORMED 5-24-57 POOL Aid

This is a Report of: (Check appropriate block) ☒ Results of Test of Casing Shut-off
☐ Beginning Drilling Operations ☐ Remedial Work
☐ Plugging ☐ Other _____

Detailed account of work done, nature and quantity of materials used and results obtained.

Ran 4-1/2" OD 9.5# casing. Set at 1,005' with 150 sacks cement. Cemented to surface. Plug down at 2:30 AM 5-24-57. Tested OK.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____
Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____
Perf Interval (s) _____
Open Hole Interval _____ Producing Formation (s) _____

| RESULTS OF WORKOVER: | BEFORE | AFTER |
|---------------------------------|--------|-------|
| Date of Test | _____ | _____ |
| Oil Production, bbls. per day | _____ | _____ |
| Gas Production, Mcf per day | _____ | _____ |
| Water Production, bbls. per day | _____ | _____ |
| Gas-Oil Ratio, cu. ft. per bbl. | _____ | _____ |
| Gas Well Potential, Mcf per day | _____ | _____ |
| Witnessed by _____ | | |

(Company)

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name M. L. Armstrong
Title Oil and Gas Inspector
Date DEC 8 1957

Name E. W. Rayton
Position District Engineer
Company Continental Oil Company

| NO. | NAME | MISSION |
|-----|------|---------|
| 1 | ... | ... |
| 2 | ... | ... |
| 3 | ... | ... |
| 4 | ... | ... |
| 5 | ... | ... |
| 6 | ... | ... |
| 7 | ... | ... |
| 8 | ... | ... |
| 9 | ... | ... |
| 10 | ... | ... |
| 11 | ... | ... |
| 12 | ... | ... |
| 13 | ... | ... |
| 14 | ... | ... |
| 15 | ... | ... |
| 16 | ... | ... |
| 17 | ... | ... |
| 18 | ... | ... |
| 19 | ... | ... |
| 20 | ... | ... |
| 21 | ... | ... |
| 22 | ... | ... |
| 23 | ... | ... |
| 24 | ... | ... |
| 25 | ... | ... |
| 26 | ... | ... |
| 27 | ... | ... |
| 28 | ... | ... |
| 29 | ... | ... |
| 30 | ... | ... |
| 31 | ... | ... |
| 32 | ... | ... |
| 33 | ... | ... |
| 34 | ... | ... |
| 35 | ... | ... |
| 36 | ... | ... |
| 37 | ... | ... |
| 38 | ... | ... |
| 39 | ... | ... |
| 40 | ... | ... |
| 41 | ... | ... |
| 42 | ... | ... |
| 43 | ... | ... |
| 44 | ... | ... |
| 45 | ... | ... |
| 46 | ... | ... |
| 47 | ... | ... |
| 48 | ... | ... |
| 49 | ... | ... |
| 50 | ... | ... |