

Allottee

Lease No. BORWELL, NEW MEXICO

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	X
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 14, 1937, 19

Well No. 5 is located 660 ft. from N line and 660 ft. from W line of sec. 22

SW/4 of Sec. 22 17S 23E N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Artesia Eddy New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

The above well was treated with 4000 gallons of acid from 2600' to 2750'. Did not respond to treatment. In fact, the treatment decreased the production.

Well produced natural approximately 25 bbls. per 24 hrs.
" " after shot 100 " " "
" " after acidizing 82 " in 48 hrs.

Work done by Dowell Incorporated.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Barnsdall Oil Company

Address Pecos, Texas Box 466

By Lawrence Mills

Title Production Clerk