

(SUBMIT IN TRIPLICATE)

U. S. Land Office Los Cruces

UNITED STATES

Lease or permit No. W. Dodd Lease

Allottee.....

DEPARTMENT OF THE INTERIOR

Serial No. - 028731A

Lease No. ....

GEOLOGICAL SURVEY

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE..... <input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

..... October 16 ....., 1957 .....

Well No. 5 is located 660 ft. from N line and 660 ft. from E line of sec. ....

38 1/4 of Sec. 22  
(1/4 Sec. and Sec. No.)

12S  
(Twp.)

22E  
(Range)

T12N  
(Meridian)

Artesia  
(Field)

753  
(County or Subdivision)

New Mexico  
(State or Territory)

The elevation of the derrick floor above sea level is ..... ft.

### DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

We wish to shoot and clean out the above described well  
for the purpose of trying to bring it back on production.

Top of shot - 2610'

Bottom of shot - 2655'

Approximately 100 lbs. of solidified glyderine.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Barnsdall Oil Company

Address Odessa, Texas Box 4472

By J. H. H. H. H. H.

Title Production Clerk