		Approval expires 12-31-52.
Form 9-381 a (Feb. 1951)	(SUBMIT IN TRIPLICATE)	Land Office
	UNITED STATES UNITED STATES	Lease No. 028784 (c) Unit
APPROVED	GEOLOGICAL SURVEY	
1	SUBDU NOTICES AND DEDODTS ON	IWEIIG

Budget Bureau 42-R358.2.

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	-
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		Auberguest Report of Hydrafrac Treatment	
		ATALATIVE ALAMATER	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

,		Loco H11	1s, X.M.	Üctobar	29 19 53
Keely C Well No 7 is locate	d 660 ft. f	rom N line ar	d 1960 ft. from	n E line of s	sec25
MK/A ME/c Sec. 25 (4 Sec. and Sec. No.)	17-5	29-5	#.X.P.X.		
(14 Sec. and Sec. No.)	(Twp.)	(Range)	(Meridian)		
Grayburg-Jackson		2447		r Merico	
(Field)	(Coun	ty or Subdivision)		(State or Territory)	

The elevation of the derrick floor above sea level is 3603. ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

PRODUCTION TENTS PRIOR TO WORKOVER: Pumped 9.00 BOPD from San Andres.

RECORD OF RECOMPLETION: On October 6, 1953 we ran Lane Wells Radioectivity Log from TD 3104' to surface then perforated from 2579-2593' w/4 - 5/32" bullets per foot. We then ran Halliburton HM Straddle Packer 2570-2610' and washed with 500 gallons Mud Acid. Swabbed oil load and acid water.

On October 9, 1953 we treated with 3000 gallons Hydrafrae containing 2# sand per gallon. Injection pressure 2800 psig. Injection rate: 6 bbls. per simute.

	(Cont.)	(must on page 2)	DEREIVEN
l understan	d that this plan of work must receive appro	Lauged on page 2) val in writing by the Geological Survey before L Company of Texas	operations may be commenced.
Company	General American 011	L Company of Texas	U ULIZ IJJJ
Address	P.O. Box 416	s ³	ARTESIA, NEW MEXICO
11441000	Loco Hills, S.M.	By	Heart
		Title	Heard, Field Supt.

U. S. GOVERNMENT PRINTING OFFICE 16-8437-4

Page 2 of Keely C-7 Subsequent Report of Hydrafrac freatment

RESULTS OF TREATMENT: After being shut in 16 hours well flowed 181 bbls. load oil and 109 bbls new oil in 24 hours thru 3/4" tubing choke.

SUBSEQUENT FLOW TESTS:

10-11-53	Flowed	135.24	BOPD	thru	16/64"	tubing	choke	w/GOR	750/1
10-12-53	Plowed	103.44	BOPD	thru	16/64"	tubing	choke	w/GOR	1010/1
10-13-53	Flowed	95.90	BOPD	thru	16/64"	tubing	choke	w/GOR	1010/1
10-14-53	Flowed	80.31	BOPD	thru	14/64"	tubing	choke	w/GOR	1070/1
10-15-53	Flowed	68.31	BOPD	thru	14/64"	tubing	choke	w/cor	1076/1
10-16-53	Flowed	58.64	BOPD	thru	12/64"	tubing	choke	w/GOR	898/1

presidents a signification and an ancher of the states of

If a set is the struct of all ture mater rates if it is in a set of a set of the set o

2 	the same atoms the of unda their galeses		
	No adalah julik ni dahilu umad Pika dalahi	ie cił	i i se
at a s	99.40 kara tara kabula kabula muka kab		to the second second
Σ^{1}	se amore paláis solutionar seus il ca	119-11月4	\$ (=) 1 = U.T
	a e class crishi haran sabar shis cici 10,30	àeno£∖	((
1	a substance and the substance of the sub	an an an an an	