

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLI
(Other instructions on re-
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.
LC-028784-C

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT -" for such proposals.)

RECEIVED

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
Phillips Petroleum Company ✓

MAR 03 '88

8. FARM OR LEASE NAME
Keely-C Fed

3. ADDRESS OF OPERATOR
Room 401, 4001 Penbrook St., Odessa, TX 79762

O. C. D.
ARTESIA, OFFICE

9. WELL NO.
43

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

10. FIELD AND POOL, OR WILDCAT
Grayburg, Jackson (SR-Q-Gb-SA)

Unit L, 2615' FSL, 25' FWL

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA
Sec. 25, T-17-S, R-29-E

14. PERMIT NO.
30-015-03112

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3850' DF

12. COUNTY OR PARISH
Eddy

13. STATE
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐ PULL OR ALTER CASING ☐
FRACTURE TREAT ☐ MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐ ABANDON* ☐
REPAIR WELL ☐ CHANGE PLANS ☐
(Other) ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐ REPAIRING WELL ☐
FRACTURE TREATMENT ☐ ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐ ABANDONMENT* ☐
(Other) Shut-in ☒

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

11-12-85: MI & RU WSU. Installed BOP. WIH w/csg scraper to 2006'.

11-13-85: WIH w/7" RBP on 2-7/8" tbg., set @ 2025'. Spt'd sand on top of RBP. Set 7" pkr. @ 600'. Tst'd csg, holes above and below 600'. Ran Csg inspection log from 2000' to 50' from surface - indicated holes from 73' to 1850' - csg had several holes in it.

11-14-85: Washed sand from RBP @ 2025' & POOH W/BP & tbg. Installed wellhead & closed well in. Well irreparable, shut in.

ACCEPTED FOR FILING

FEB 26 1988

SJS
CAPITOL, ALBUQUERQUE, NEW MEXICO

RECEIVED
FEB 10 10 57 AM '88

18. I hereby certify that the foregoing is true and correct

SIGNED W. J. Mueller TITLE Engineering Supv., Reservoir DATE February 5, 1988

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

3160-5-Keely C Fed