
30-45-03/4

OFF 20 # 24164

Dup 16436

Pool - 28509

4-10-93 WIW L-4502



Submit 3 Copies To Appropriate District	State of N	lew Mex	ico		Form C-103
Office District I	Energy, Minerals and Natural Resources			Revised March 25, 1999	
1625 N. French Dr., Hobbs, NM 88240	Tital Dis tritian and and transmit transmit and			WELL API NO.	
District II	OIL CONSERVATION DIVISION		30-015-03146		
811 South First, Artesia, NM 88210			5. Indicate Type o	f Lease	
District III 1000 Rio Brazos Rd., Aztec, NM 87410	2040 South Pacheco		STATE □ FEE ☒		
District IV	Santa Fe, NMI 8/303			6. State Oil & Ga	is Lease No.
2040 South Pacheco, Santa Fe, NM 87505			LC – 028775 (A)		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				7. Lease Name or Unit Agreement Name:	
1. Type of Well:				Robinson Jackson	Unit Tract I
Oil Well Gas Well					
2. Name of Operator				8. Well No. 9	
Vintage Drilling LLC					7*1 1
3. Address of Operator				9. Pool name or V	
P.O. Box 158 Loco Hills, NM 88255				Grayburg-Jacksor	(Keely)
4. Well Location					
Unit Letter O	: 660 feet from the	South	line and	1980 feet from	n the <u>East</u> line
Section 27	Township	17S	Range 29E	NMPM E	ddy County
Section 21	10. Elevation (Show w				
	3556 GR		, , , ,		
11. Check A	Appropriate Box to Inc	dicate Na	ture of Notice,	Report or Other 1	Data
	NTENTION TO:		SUB	SÉQUENT REI	PORT OF:
PERFORM REMEDIAL WORK			REMEDIAL WOR		ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DR	ILLING OPNS.	PLUG AND
BUIL OF ALTER CACING]		CASING TEST A	ND \square	ABANDONMENT
PULL OR ALTER CASING L.	MULTIPLE COMPLETION		CEMENT JOB	ND [_]	
OTHER:			OTHER:		
12. Describe proposed or comple of starting any proposed work	eted operations. (Clearly so k). SEE RULE 1103. For	tate all peri Multiple C	tinent details, and gompletions: Attac	give pertinent dates, th wellbore diagram	of proposed completion
or recompilation.					00.21
Well Failed MIT test.				3723	RECEIVED ARTESIA TO JOD - ARTESIA
Repaired hole in tubing.			2	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	(12)
Well Failed MIT test. Repaired hole in tubing. Perforated 2464' to 2480', 2506' to 2512' (as per sundry notice of 4/11/00) Tested casing to 300# for 15 minutes. Tested ok. Chart to NMOCCD. RECENSOR OCD ARTESIA					
Tested casing to 300# for 15 minutes. Tested ok.					
Chart to NMOCCD.				/3/ C	100. ARTS 3
				\ce_i \	.67/
				~02°	
				```	81 21 91 91
			_		
I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
SIGNATURE () () SI	· Luka	TITLE	Secretary	DATE	11/28/00
SIGNATIONAL TO WA	1 Collins	IIILE			
	Marie Durham		ı elepn	one No. 505-748-2	.7T1
(This space for State use)					

FOURTH P5000 OK HOT DI VINTALE ORILLIANS